

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10069B

Date In: 13 FEB 24 Author: MGRAY
Promised Date: 31 MAY 25 Stock No: 11082
: Year: 2022
Customer Name: 17385 - WILLIAMS, JEFF Manufacturer: FOREST RIVER
Address: 980 ARCHERS WAY Brand: PUMA TT
: NEKOOSA, WI Model: 25BHFQ
Postal/Zip: 54457 Miles/Hrs: 0
Phone#(res): 7154516222 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: JKWILL10@GMAIL.COM Tag#:
Purchased Date: 20 JUN 24 :
Delivery Date: 28 JUN 24 :
InService Date: :
Serial#: 5ZT2PUPB7N4016293 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - TRIM ON FOLDABLE WALL	WARRANTY REPAIR 1 - TRIM ON FOLDABLE WALL	W	1021 FORES
	CAUSE: Trim on foldable wall not secured			
	CORRECTION: Secured to aluminum tubing, sits well now			
WARR	COMPLAINT: WARRANTY REPAIR 2 - SCREW RAN TOO FAR, BUNK CAN SEE IN METAL OUTSIDE S/O	WARRANTY REPAIR 2 - SCREW RAN TOO FAR, BUNK CAN SEE IN METAL OUTSIDE S/O	W	1021 FORES
	CAUSE: Screw in bunk ran too deep can see in s/o metal			
	CORRECTION: Backed off screw so no further damage can occur			
WARR	COMPLAINT: WARRANTY REPAIR 3 - CRACKED CELING PANEL	WARRANTY REPAIR 3 - CRACKED CELING PANEL	W	1021 FORES
	CAUSE: Crack in ceiling panel ac duct straight from entry door between duct and panel			
	CORRECTION: Puttied and noting			
WARR	COMPLAINT: WARRANTY REPAIR 4 - MARKER LIGHT OUT	WARRANTY REPAIR 4 - MARKER LIGHT OUT	W	1021 FORES
	CAUSE: Side marker light bad			
	CORRECTION: Replaced and resealed and tested			
WARR	COMPLAINT: WARRANTY REPAIR 5 - LED IN SPEAKER LIGHT OUT	WARRANTY REPAIR 5 - LED IN SPEAKER LIGHT OUT	W	1021 FORES
	CAUSE: Speaker light out			
	CORRECTION: Replaced speaker with new hooked up and tested, resealed			
WARR	COMPLAINT: WARRANTY REPAIR 6 -DECALS ON FRONT CAP PEELING	WARRANTY REPAIR 6 -DECALS ON FRONT CAP PEELING	W	1021 FORES
	CAUSE: Decals ordered does not cover what's needed, need to order more decals, got with service advisors to order rest put			

Continued on page 2

Work Order : 10069B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                others in parts Start taking decals off.
CORRECTION: During the decal replacement process,
the puma decal came in deformed. Will
need to reorder new decal. Pics
uploaded. In the process of cleaning the
front cap, the finish of the paint ware
through and left a blemish. Front and
decals need to be replaced.
WARR   COMPLAINT:  WARRANTY REPAIR 7 - ROOF SEVERAL RESEAL W    1021   FORES
POINTS
CAUSE:      Roof needs to be resealed in several spots
in black silicone, clear silicone and
white dicor
CORRECTION: All spots resealed properly
WARR   COMPLAINT:  WARRANTY REPAIR 8 - SEWER CAPS ARE W    1021   FORES
MISSING
CAUSE:      Sewer caps on both drains missing
CORRECTION: Replaced
1      COMPLAINT:  THE DOOR SIDE FENDER SKIRT IS CRACKED W    1021   FORES
AND NEEDS TO BE REPLACED
CAUSE:      Fender skirt replacement.
CORRECTION: Installed new fender skirt.
WARR   COMPLAINT:  WARRANTY REPAIR 25 rear cabinet door ods W    1021   FORES
upper got torn off during operation of
rear slide.
CAUSE:      Damaged cabinet on rear of unit upper
ods. Need new door. 10"x21".
CORRECTION: Install new cabinet door next to bunk
slide in rear of unit.

```

```

*****
Job # Part No      Description           PARTS      Bill to   Qty   Price   Total
*****
WARR0 822071312      RED MARKER LIGHT           W-1021     1     2.85    2.85
WARR0 822055706      SPEAKER, 5-1/4" BLACK, O W-1021     1    11.58   11.58
WARR0 822024266      DECAL, PUMA, FRONT DIE C W-1021     1    14.91   14.91
WARR0 822025039      DECAL, PUMA, FRONT DIE C W-1021     1     9.07    9.07
WARR0 822024265      DECAL, PUMA, FRONT DIE C W-1021     1    14.91   14.91
WARR0 822024267      DECAL, PUMA, FRONT DIE C W-1021     1     6.16    6.16
WARR0 822024268      DECAL, PUMA, FRONT DIE C W-1021     1     6.16    6.16
WARR0 822025036      DECAL, PUMA, FRONT DIE C W-1021     1    37.12   37.12
WARR0 822025024      DECAL, PUMA, FRONT DIE C W-1021     1     8.09    8.09
WARR0 822025030      DECAL, PUMA, FRONT DIE C W-1021     1    13.39   13.39
WARR0 822025047      DECAL, PUMA, FRONT DIE C W-1021     1    17.13   17.13
WARR0 822025048      DECAL, PUMA, FRONT DIE C W-1021     1    19.53   19.53
WARR0 822024836      DECAL, PUMA, LG PUMA LEG W-1021     1    53.37   53.37
WARR0 822024837      DECAL, PUMA, PALOMINO LE W-1021     1    14.35   14.35
WARR0 816227010643  PLASTIC DOOR ASSEMB/WF89 W-1021     1    38.44   38.44
WARR0 019079102003  BAYONET CAP                W-1021     2     2.12    4.24

```

Continued on page 3

Work Order : 10069B

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
1      F100189269     FENDERSKIRT, TANDEM, PUM W-1021      1      33.23      33.23
WARR2 82203080      CABINET DOOR FLAT PANEL W-1021      1      25.29      25.29
WARR2 82205985      PULL CAB DOOR / BLACK   W-1021      1      1.89      1.89
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR DL W-1021      0.10      115.00      11.50
ARR02 Z992      MISC LABOUR CODE (WARR DL W-1021      0.20      115.00      23.00
ARR03 Z992      MISC LABOUR CODE (WARR DL W-1021      0.20      115.00      23.00
ARR04 Z992      MISC LABOUR CODE (WARR DL W-1021      0.18      115.00      20.70
ARR04 Z992      MISC LABOUR CODE (WARR DL W-1021      0.02      115.00      2.30
ARR05 Z992      MISC LABOUR CODE (WARR DL W-1021      0.18      115.00      20.70
ARR05 Z992      MISC LABOUR CODE (WARR DL W-1021      0.02      115.00      2.30
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR DL W-1021      0.03      115.00      3.45
ARR06 Z992      MISC LABOUR CODE (WARR DL W-1021      0.03      115.00      3.45
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.02      115.00      2.30
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.42      115.00      48.30
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
ARR07 Z992      MISC LABOUR CODE (WARR DL W-1021      0.02      115.00      2.30
ARR07 Z992      MISC LABOUR CODE (WARR DL W-1021      0.20      115.00      23.00
ARR08 Z992      MISC LABOUR CODE (WARR DL W-1021      0.00      115.00      0.00
ARR08 Z992      MISC LABOUR CODE (WARR DL W-1021      0.10      115.00      11.50
1 WARR      MANUFACTURER WARRANTY TD W-1021      0.50      115.00      57.50
ARR25 Z992      MISC LABOUR CODE (WARR TD W-1021      0.50      115.00      57.50
ARR25 WARR      MANUFACTURER WARRANTY TD W-1021      0.00      115.00      0.00
ARR25 WARR      MANUFACTURER WARRANTY TD W-1021      0.50      115.00      57.50
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.29      115.00      33.35
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.21      115.00      24.15
ARR06 Z992      MISC LABOUR CODE (WARR TD W-1021      0.00      115.00      0.00
*****
```

```
*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL W-1021      1.00      0.00      0.00
ARR06  FRT     FREIGHT FOR DECALS 4/19 W-1021      1.00      31.90      31.90
ARR06  FRT     FREIGHT FOR PO 121452   W-1021      1.00      75.27      75.27
ARR06  FRT     FREIGHT                 W-1021      1.00      39.08      39.08
1 FRT     FREIGHT                 W-1021      1.00      32.88      32.88
ARR25  FRT     FREIGHT                 W-1021      1.00      21.05      21.05
*****
```

Continued on page 4

Work Order : 10069B

CUSTOMER COMMENTS

Freight-47.91-KW

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	331.71	427.80	0.00	200.18	0.00	959.69
	Totals	331.71	427.80	0.00	200.18	0.00	959.69

&k2S
&k0S