

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10069B

Date In: 13 FEB 24 Author: MGRAY
Promised Date: 31 DEC 24 Stock No: 11082
: Year: 2022
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA TT
: CHICAGO, IL Model: 25BHFQ
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: NOW SOLD TO WILLIAMS
Purchased Date: 20 JUN 24 :
Delivery Date: 28 JUN 24 :
InService Date: :
Serial#: 5ZT2PUPB7N4016293 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - TRIM ON FOLDABLE W W 1021 FORES
WALL
CAUSE: Trim on foldable wall not secured
CORRECTION: Secured to aluminum tubing, sits well
now
WARR COMPLAINT: WARRANTY REPAIR 2 - SCREW RAN TOO FAR, W W 1021 FORES
BUNK CAN SEE IN METAL OUTSIDE S/O
CAUSE: Screw in bunk ran too deep can see in
s/o metal
CORRECTION: Backed off screw so no further damage
can occur
WARR COMPLAINT: WARRANTY REPAIR 3 - CRACKED CELING PANEL W W 1021 FORES
CAUSE: Crack in ceiling panel ac duct straight
from entry door between duct and panel
CORRECTION: Puttied and noting
WARR COMPLAINT: WARRANTY REPAIR 4 - MARKER LIGHT OUT W W 1021 FORES
CAUSE: Side marker light bad
CORRECTION: Replaced and resealed and tested
WARR COMPLAINT: WARRANTY REPAIR 5 - LED IN SPEAKER LIGHT W W 1021 FORES
OUT
CAUSE: Speaker light out
CORRECTION: Replaced speaker with new hooked up and
tested, resealed
WARR COMPLAINT: WARRANTY REPAIR 6 -DECALS ON FRONT CAP W W 1021 FORES
PEELING
CAUSE: Decals on front cap mostly all peeling
need to get with Shawn and Matt on how
to proceed

Continued on page 2

Work Order : 10069B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: .
WARR    COMPLAINT:  WARRANTY REPAIR 7 - ROOF SEVERAL RESEAL W    1021    FORES
          POINTS
          CAUSE:      Roof needs to resealed in several spots
                    in black silicone, clear silicone and
                    white dicor
          CORRECTION: All spots resealed properly
WARR    COMPLAINT:  WARRANTY REPAIR 8 - SEWER CAPS ARE          W    1021    FORES
          MISSING
          CAUSE:      Sewer caps on both drains missing
          CORRECTION: Replaced
1       COMPLAINT:  THE DOOR SIDE FENDER SKIRT IS CRACKED      W    1021    FORES
          AND NEEDS TO BE REPLACED
          CAUSE:      Fender skirt replacement.
          CORRECTION: Installed new fender skirt.
WARR    COMPLAINT:  WARRANTY REPAIR 25 rear cabinet door ods W    1021    FORES
          upper got torn off during operation of
          rear slide.
          CAUSE:      Damaged cabinet on rear of unit upper
                    ods. Need new door. 10"x21".
          CORRECTION: ....
  
```

```

*****
Job # Part No   Description                PARTS   Bill to   Qty   Price   Total
*****
WARR0 822071312   RED MARKER LIGHT           W-1021   1     2.85    2.85
WARR0 822055706   SPEAKER, 5-1/4" BLACK, O W-1021   1    11.58   11.58
WARR0 822024266   DECAL, PUMA, FRONT DIE C W-1021   1    14.91   14.91
WARR0 822025039   DECAL, PUMA, FRONT DIE C W-1021   1     9.07    9.07
WARR0 822024265   DECAL, PUMA, FRONT DIE C W-1021   1    14.91   14.91
WARR0 822024267   DECAL, PUMA, FRONT DIE C W-1021   1     6.16    6.16
WARR0 822024268   DECAL, PUMA, FRONT DIE C W-1021   1     6.16    6.16
WARR0 822025036   DECAL, PUMA, FRONT DIE C W-1021   1    37.12   37.12
WARR0 822025024   DECAL, PUMA, FRONT DIE C W-1021   1     8.09    8.09
WARR0 822025030   DECAL, PUMA, FRONT DIE C W-1021   1    13.39   13.39
WARR0 822025047   DECAL, PUMA, FRONT DIE C W-1021   1    17.13   17.13
WARR0 822025048   DECAL, PUMA, FRONT DIE C W-1021   1    19.53   19.53
WARR0 822024836   DECAL, PUMA, LG PUMA LEG W-1021   1    53.37   53.37
WARR0 822024837   DECAL, PUMA, PALOMINO LE W-1021   1    14.35   14.35
WARR0 816227010643 PLASTIC DOOR ASSEMB/WF89 W-1021   1    38.44   38.44
WARR0 019079102003 BAYONET CAP                W-1021   2     2.12    4.24
1      F100189269   FENDERSKIRT, TANDEM, PUM W-1021   1    33.23   33.23
WARR2 82203080     CABINET DOOR FLAT PANEL W-1021   0    25.29    0.00
  
```

```

*****
Job# Lab Code Description    LABOUR   Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992   MISC LABOUR CODE (WARR DL W-1021   0.10  115.00  11.50
ARR02 Z992   MISC LABOUR CODE (WARR DL W-1021   0.20  115.00  23.00
  
```

Continued on page 3

Work Order : 10069B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR03 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.20   115.00   23.00
ARR04 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.18   115.00   20.70
ARR04 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.02   115.00    2.30
ARR05 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.18   115.00   20.70
ARR05 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.02   115.00    2.30
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.00   115.00    0.00
ARR06 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.03   115.00    3.45
ARR06 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.03   115.00    3.45
ARR07 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.02   115.00    2.30
ARR07 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.20   115.00   23.00
ARR08 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.00   115.00    0.00
ARR08 Z992      MISC LABOUR CODE (WARR DL  W-1021    0.10   115.00   11.50
   1 WARR      MANUFACTURER WARRANTY TD  W-1021    0.50   115.00   57.50
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.00   115.00    0.00
ARR25 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.50   115.00   57.50
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.02   115.00    2.30
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.42   115.00   48.30
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.00   115.00    0.00
ARR06 Z992      MISC LABOUR CODE (WARR TD  W-1021    0.00   115.00    0.00
*****
```

```
*****
Job #  Excode   Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00
ARR06  FRT       FREIGHT FOR DECALS 4/19  W-1021    1.00   31.90   31.90
ARR06  FRT       FREIGHT FOR PO 121452  W-1021    1.00   75.27   75.27
   1 FRT       FREIGHT  W-1021    1.00   32.88   32.88
ARR06  FRT       FREIGHT  W-1021    1.00   39.08   39.08
ARR25  FRT       FREIGHT  W-1021    1.00   21.05   21.05
*****
```

CUSTOMER COMMENTS

Freight-47.91-KW

BILLINGS SUMMARY

```
*****
Type Bill Id    Parts  Labour  Sublet  Extras  Tax  Total
*****
W      1021      304.53  312.80   0.00   200.18  0.00   817.51
*****
Totals      304.53  312.80   0.00   200.18  0.00   817.51
*****
```

&k2S
&k0S