

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10072B

Date In: 12 FEB 24 Author: MGRAY  
Promised Date: 04 JUL 24 Stock No: 11092  
: Year: 2023  
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER  
Address: 8220 STATE HWY 13 SOUT Brand: PUMA TT  
: WISCONSIN RAPIDS, WI Model: 25BHSC  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): 800-758-2272 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: 28 JAN 24 :  
Delivery Date: 10 FEB 24 :  
InService Date: :  
Serial#: 5ZT2PUPB6P4017924 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
DAF	COMPLAINT:	DAF-WARRANTY REPAIRS- 1.BEDROOM DOOR FRAME NEAR KITCHEN COUNTER EDGE OFF AND WALL PANEL BUBBLE 2.WITH SLIDE IN BY KITCHEN COUNTER, SLIDE OUT SEAL IS HANGING. 3. CEILING HAS PUTTY ALL OVER 4.DINETTE TABLE SCRATCHES AND A BLOB ON IT.	I	PDI PRE-D
WARR	CORRECTION:	LOOKED AT ALL REPAIRS NEEDED		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Bathroom vent INTERIOR SHROUD is cracked	W	1021 FORES
	CAUSE:	SHROUD is cracked		
WARR	CORRECTION:	Replaced it with new one		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - Shower head not working	W	1021 FORES
	CAUSE:	Shower head not working INTERNAL FAILURE		
	CORRECTION:	Something blocking it HAD TO REPLACE IT AND CHECKS OK		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - Bedroom door frame Near counter, panel is bubbled	W	1021 FORES
	CAUSE:	Pocket door out of alignment and wall panel balging		
	CORRECTION:	Fixed wall panel still has slit bulge pocket door is still kinda out of Alignment due to selling saging nothing I can do		
WARR	COMPLAINT:	WARRANTY REPAIR 6 - Screw track on off door side of camper is coming off.	W	1021 FORES
	CAUSE:	Joe fixed it		

Continued on page 2

Work Order : 10072B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CORRECTION: .
WARR    COMPLAINT:  WARRANTY REPAIR 7 - water heater not      W    1021    FORES
          working
          CAUSE:      Water heater not lighting
          CORRECTION: Problem with the ground now it's working

WARR    COMPLAINT:  WARRANTY REPAIR 8 - Marker light not      W    1021    FORES
          working on on door side going to remove
          marker light from vin#0714 so when part
          comes in for it install on this stock
          unit.
          CAUSE:      Side marker light not working due to
          water damage Need to order parts
          installed one for temporary
          CORRECTION: ..
*****
```

```
*****
Job # Part No      Description           PARTS   Bill to   Qty    Price    Total
*****
WARR0 834834209205  GARNISH REPLACEMENT - 4- W-1021    1     12.90    12.90
WARR0 019079642547  HH SHW HEAD, WT         W-1021    1      9.00     9.00
WARR0 756815101110  100FT PREMIUM VINYL INSE W-1021    1     24.74    24.74
WARR0 822071312     RED MARKER LIGHT        W-1021    1      2.85     2.85
*****
```

```
*****
Job# Lab Code  Description           LABOUR   Mech Bill to   Hrs    Rate    Total
*****
  DAF Z991    DAF-WARRANTY REPAIR           I-PDI    0.00    70.00    0.00
  DAF Z991    DAF-WARRANTY REPAIR           NCN I-PDI    0.01    70.00    0.70
ARR02 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.30   115.00   34.50
ARR02 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR02 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.20   115.00   23.00
ARR03 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR03 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR03 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.50   115.00   57.50
ARR05 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR05 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.50   115.00   57.50
ARR05 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR06 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.46   115.00   52.90
ARR06 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.04   115.00    4.60
ARR07 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.50   115.00   57.50
ARR07 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR08 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.00   115.00    0.00
ARR08 Z992    MISC LABOUR CODE (WARR NCN W-1021    0.50   115.00   57.50
*****
```

Continued on page 3

Work Order : 10072B

\*\*\*\*\*

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	0.70	0.00	0.00	0.00	0.70
W	1021	49.49	345.00	0.00	0.00	0.00	394.49
	Totals	49.49	345.70	0.00	0.00	0.00	395.19

&k2S  
&k0S