

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 1991086
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2PUPB6P4017924
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 425 / 425
 ITEM # PUT25BHSC-425
 DEALER RO # 10072B
 CLAIM START DATE 07/19/2024
 CLAIM END DATE 07/19/2024

Labor rate: \$115.00

OWNER INFORMATION

JASON WENZEL
 216800 CTY RD Q
 Hatley, WI 54440
 USA

Retail Date of Purchase 02/10/2024

WARRANTY EXPIRATION DATE 02/10/2025

Claim Line Details

Labor

Line# 1	Operation Code 20-62-01-00-000650	Operational Description Interior Vent Garnish - Exterior/Power Roof Vent (Elixir & Hengs)/Replace/No Tread Code
---------	--------------------------------------	--

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-07-19 12:52:54 :: Bathroom vent interior shroud is cracked. Cracked upon delivery of unit. Replaced with new one. ***Creating claim for PARTS ONLY. Labor will be submitted at zero as this in pending payment on Claim # 183 Additional Note : greeneway@dealer-advisors.com, 2024-07-19 12:53:25 :: Claim # 1837418

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part

Line# 1	Item # USERPART	Description 834834209205-WHITE GARNISH REPLACEMENT 4.5"
	Model #	Serial # Part tag
	Sub Qty 1.00	Sub Dlr Price \$12.90 Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$12.90 Appr Freight \$0.00

Notes

Labor

Line# 2	Operation Code 60-141-01-00-001583	Operational Description Interior Shower Head & Hose (Read Notes!!!) - Plumbing/Shower, Tub Surround/Replace/No Tread Code
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-07-19 13:16:15 :: Shower head not working INTERNAL FAILURE, Something blocking it HAD TO REPLACE IT AND CHECKS OK ***Parts ONLY. Labor submitted on 1837418.

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part

Line# 1	Item # USERPART	Description 019079642547- HH SHW HEAD, WT.
	Model #	Serial # Part tag

Sub Qty	1.00	Sub Dlr Price	\$9.00	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$9.00	Appr Freight	\$0.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 20-58-01-00-002310 Vinyl Insert (per 10') - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2024-07-19 13:32:14 :: Screw track on off door side of camper is coming off. technician resecured it ****Claiming PART ONLY.

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part

Line# 1 **Item #** **Description**
 USERPART 756815101110- 100FT PREMIUM VINYL INSERT.
Model # **Serial #** **Part tag**
 Sub Qty 1.00 Sub Dlr Price \$24.74 Sub Freight \$0.00
 Appr Qty 1.00 Appr Dlr Price \$24.74 Appr Freight \$0.00

Notes

Labor

Line# 4 **Operation Code** **Operational Description**
 40-106-01-12-001216 Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2024-07-19 13:35:10 :: Marker light not working on on door side Side marker light not working due to water damage Need to order parts ****Claim for PART ONLY.

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part

Line# 1 **Item #** **Description**
 F100271312 LIGHT, LED RED OVAL MARKER, BLACK BASE, (DREAM) #CMO3-SRR
Model # **Serial #** **Part tag**
 Sub Qty 1.00 Sub Dlr Price \$1.54 Sub Freight \$0.00
 Appr Qty 1.00 Appr Dlr Price \$1.55 Appr Freight \$0.00

Notes

Submitted	Labor Amt	\$0.00	Approved	Labor Amt	\$0.00
	Parts & Freight	\$48.18		Parts & Freight	\$48.19
	Total	\$48.18		Total	\$48.19

 DEALER DATE
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

 CUSTOMER DATE
 SIGNATURE

All repairs described have been inspected and are satisfactory.