

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	1837418
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUPB6P4017924
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$115.00	ITEM #	PUT25BHSC-425
OWNER INFORMATION		DEALER RO #	10072B
JASON WENZEL		CLAIM START DATE	03/04/2024
216800 CTY RD Q		CLAIM END DATE	07/18/2024
Hatley, WI 54440			
USA			
Retail Date of Purchase	02/10/2024	WARRANTY EXPIRATION DATE	02/10/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-62-01-00-000650	Interior Vent Garnish - Exterior/Power Roof Vent (Elixir & Hengs)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : afreeman@greenewayrv.com, 2024-03-04 10:59:59 :: Bathroom vent INTERIOR SHROUD is cracked, CRACKED UPON DELIVERY OF UNIT, Replaced it with new one			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$11.50	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$11.50	
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-141-01-00-001583	Interior Shower Head & Hose (Read Notes!!!) - Plumbing/Shower, Tub Surround/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : afreeman@greenewayrv.com, 2024-03-04 11:02:15 :: Shower head not working INTERNAL FAILURE, Something blocking it HAD TO REPLACE IT AND CHECKS OK			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$11.50	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$11.50	
	Notes			

Labor

Line# 3	Operation Code		Operational Description	
	20-70-02-00-000715		Access Door - Exterior/Access Doors/Adjust/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : afreeman@greenewayrv.com, 2024-03-04 11:22:31 :: Bedroom door frame Near counter, panel is bubbled, Pocket door out of alignment and wall panel bulging. Fixed wall panel still has slit bulge pocket door is still kinda out of Alignment due to selling sagging. Cannot be repaired any further may need to replace in the future.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$23.00	
Serial#	Appr Hrs	0.20	Appr Labor Amt \$23.00	
Notes				

Labor

Line# 4	Operation Code	Operational Description
	20-58-01-00-002310	Vinyl Insert (per 10') - Exterior/Metal, Aluminum Siding/Replace/No Tread Code
	Complaint, Cause, Correction	

Original Note : afreeman@greenewayrv.com, 2024-03-04 11:43:39 :: Screw track on off door side of camper is coming off. technician resecured it.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$11.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$11.50

Notes

Labor
Line# 5

Operation Code	Operational Description
40-106-01-12-001216	Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting

Complaint, Cause, Correction

Original Note : afreeman@greenewayrv.com, 2024-03-04 11:55:33 :: Marker light not working on on door side
Side marker light not working due to water damage Need to order parts

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$23.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$23.00

Notes

Submitted	Labor Amt	\$80.50	Approved	Labor Amt	\$80.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$80.50		Total	\$80.50

DEALER
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

DATE

CUSTOMER
SIGNATURE
All repairs described have been inspected and are satisfactory.

DATE