



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

spreading the joy of the camping lifestyle

(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com

W/O: 10074B
Promised Date:



WO #: 10074B

Customer Name: 1000 - GREENEWAY RV
SALES & SERVICE

Address: 8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS, WI

Postal/Zip: 54494

Phone#(res): 800-758-2272

Phone#(bus):

Cell Phone:

Email: NONE

Date In: 23 FEB 24

Promised Date: 04 JUL 24

Purchased Date:

Delivery Date:

InService Date:

Serial#: 5ZT2PURB6N4016461

Author: MGRAY

Stock No: 11084

Year: 2022

Manufacturer: FOREST RIVER

Brand: PUMA TT

Model: 26FKDS

Miles/Hrs: 0

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#: ENTERED DB 6/6

Job #WARR01 - Warranty

COMPLAINT: WARRANTY REPAIR 1 -trim above kitchen is coming off

CAUSE: Trim coming off wall

CORRECTION: Nailed trim back into place

Labor

Job #	Description	Total
WARR01	MISC LABOUR CODE (WARRANTY)	11.50

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES - EXTERNAL	1.00	0.00	0.00

Subtotal for Job #WARR01: 11.50

Job #WARR02 - Warranty

COMPLAINT: WARRANTY REPAIR 2 - Bedroom rear window is missing screw

CAUSE: Missing screws

CORRECTION: Fixed and put in missing screw

Labor

Job #	Description	Total
WARR02	MISC LABOUR CODE (WARRANTY)	11.50

Subtotal for Job #WARR02: 11.50

Job #WARR03 - Warranty

COMPLAINT: WARRANTY REPAIR 3 - Bathroom is missing panel in shower

CAUSE: I removed the outer panel, hung the interior panel, and put the outer panel back on. Their is still a lot of glass in between the shroud and frame and I can't get it all out so I filled the gap with silicone to prevent anymore glass shards coming out into the shower base. I vacuumed up anymore glass that I found.

CORRECTION: Done.

Labor

Job #	Description	Total
WARR03	MISC LABOUR CODE (WARRANTY)	5.75

Customer #: 1000
GREENEWAY RV SALES &
SERVICE,





Parts				
Part #	Description	Qty	Price	Total
82200002	FAN GARNISH RING WHITE 4" MAXXAIR	1.00	24.05	24.05
822021967	SHOWER, FIXED GLASS, 34", USED ON BOTH LH & RH SIDE OF DOOR (2 PER SHOWER), D34-200	1.00	53.63	53.63

Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	91.02	91.02

Subtotal for Job #WARR03: 174.45

Job #WARR04 - Warranty

COMPLAINT: WARRANTY REPAIR 4 - Bathroom vent Valance is cracked

CAUSE: Valance was cracked

CORRECTION: Replaced with new

Labor		
Job #	Description	Total
WARR04	MISC LABOUR CODE (WARRANTY)	23.00

Subtotal for Job #WARR04: 23.00

Job #WARR06 - Warranty

COMPLAINT: MISSING BUMPER COVER

CAUSE: . MISSING BUMPER COVER

CORRECTION: .REPLACED BUMPER COVER

Labor		
Job #	Description	Total
WARR06	MISC LABOUR CODE (WARRANTY)	46.00

Parts				
Part #	Description	Qty	Price	Total
756815106658	LOW PROFILE BUMPER DOOR H	1.00	11.45	11.45

Subtotal for Job #WARR06: 57.45

Job #WARR07 - Warranty

COMPLAINT: WARRANTY REPAIR 7 - Shower faucet leaking

- warranty states they need further pictures for authorization. Requests pictures of complete faucet, as well as tag underside of faucet.

CAUSE: Leaky faucet.

I replaced the hose.

CORRECTION: Done.

Labor		
Job #	Description	Total
WARR07	MULTIPLE LABOR CODES	34.50

Parts				
Part #	Description	Qty	Price	Total
822071118	SHOWER HOSE KIT, MATTE BLACK, #SA130-MB	1.00	11.19	11.19



Subtotal for Job #WARR07: 45.69

Job #WARR08 - Warranty

COMPLAINT: WARRANTY REPAIR 8 - The bedroom slide out switch is reversed and it sticks.

CAUSE: 1000 DEFECT FROM MANUFACTURER.

I pulled the switch out and flipped it. I ran it a few more times, and the button didn't stick again.

CORRECTION: Done.

Labor

Job #	Description	Total
WARR08	MISC LABOUR CODE (WARRANTY)	11.50

Subtotal for Job #WARR08: 11.50

Job #WARR09 - Warranty

COMPLAINT: WARRANTY REPAIR 9 - The baton strip to the left of the shower is ripped.

CAUSE: The baton strip is coming off.

We don't have this style, so I touched it up with putty and went along the top edge of it with silicone. The job took .3 to complete

CORRECTION: Done.

Labor

Job #	Description	Total
WARR09	MISC LABOUR CODE (WARRANTY)	11.50

Subtotal for Job #WARR09: 11.50

Job #WARR10 - Warranty

COMPLAINT: WARRANTY REPAIR 10 - The cabinet door under the sink won't close and latch.

CAUSE: The screws that secure the latch to the cabinet frame are too short and pulled out. I put longer screws in.

CORRECTION: Done.

Labor

Job #	Description	Total
WARR10	MISC LABOUR CODE (WARRANTY)	11.50

Subtotal for Job #WARR10: 11.50

Parts Total: 100.32
Labour Total: 166.75
Sublet Total: 0.00
Extras Total: 91.02

WORK ORDER TOTAL: 358.09

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.

I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : _____

Date: 07 Jun 2024

W/O: 10074B
Promised Date: 04 JUL 24



Customer #: 1000
GREENWAY RV SALES &
SERVICE,

