

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10074B

Date In: 23 FEB 24 Author: MGRAY
Promised Date: 04 JUL 24 Stock No: 11084
: Year: 2022
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA TT
: CHICAGO, IL Model: 26FKDS
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: ADDED PICS FOR FAUCET
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 5ZT2PURB6N4016461 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 -trim above kitchen is W 1021 FORES
coming off
CAUSE: Trim coming off wall
CORRECTION: Nailed trim back into place
WARR COMPLAINT: WARRANTY REPAIR 2 - Bedroom rear window W 1021 FORES
is missing screw
CAUSE: Missing screws
CORRECTION: Fixed and put in missing screw
WARR COMPLAINT: WARRANTY REPAIR 3 - Bathroom is missing W 1021 FORES
panel in shower
CAUSE: I removed the outer panel, hung the
interior panel, and put the outer panel
back on. Their is still a lot of glass
in between the shroud and frame and I
can't get it all out so I filled the gap
with silicone to prevent anymore glass
shards coming out into the shower base.
I vacuumed up anymore glass that I
found.
CORRECTION: Done.
WARR COMPLAINT: WARRANTY REPAIR 4 - Bathroom vent W 1021 FORES
Valence is cracked
CAUSE: Valance was cracked
CORRECTION: Replaced with new
WARR COMPLAINT: MISSING BUMPER COVER W 1021 FORES
CAUSE: . MISSING BUMPER COVER
CORRECTION: .REPLACED BUMPER COVER
WARR COMPLAINT: WARRANTY REPAIR 7 - Shower faucet W 1021 FORES

Continued on page 2

Work Order : 10074B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
leaking - warranty states they need
further pictures for authorization.
Requests pictures of complete faucet, as
well as tag underside of faucet.
CAUSE:   Leaky faucet. I replaced the hose.
CORRECTION: Done.
WARR    COMPLAINT:  WARRANTY REPAIR 8 - The bedroom slide   W    1021   FORES
out switch is reversed and it sticks.
CAUSE:   1000 DEFECT FROM MANUFACTURER. I pulled
the switch out and flipped it. I ran it
a few more times, and the button didn't
stick again.
CORRECTION: Done.
WARR    COMPLAINT:  WARRANTY REPAIR 9 - The baton strip to   W    1021   FORES
the left of the shower is ripped.
CAUSE:   The baton strip is coming off. We don't
have this style, so I touched it up with
putty and went along the top edge of it
with silicone. The job took .3 to
complete
CORRECTION: Done.
WARR    COMPLAINT:  WARRANTY REPAIR 10 - The cabinet door   W    1021   FORES
under the sink won't close and latch.
CAUSE:   The screws that secure the latch to the
cabinet frame are too short and pulled
out. I put longer screws in.
CORRECTION: Done.

```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 82200002      FAN GARNISH RING WHITE 4 W-1021   1     24.05   24.05
WARR0 822021967      SHOWER, FIXED GLASS, 34" W-1021   1     53.63   53.63
WARR0 134337         GARNISH JENSEN/ELIXIR/VE W-1021   0     22.37   0.00
WARR0 756815106658  LOW PROFILE BUMPER DOOR W-1021   1     11.45   11.45
WARR0 822071118      SHOWER HOSE KIT, MATTE B W-1021   1     11.19   11.19

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.00 115.00 0.00
ARR01 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.50 115.00 57.50
ARR02 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.00 115.00 0.00
ARR02 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.50 115.00 57.50
ARR03 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.00 115.00 0.00
ARR03 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.50 115.00 57.50
ARR04 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.00 115.00 0.00
ARR04 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.50 115.00 57.50
ARR06 Z992 MISC LABOUR CODE (WARR NCN W-1021 0.50 115.00 57.50

```

Continued on page 3

Work Order : 10074B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR06 Z992      MISC LABOUR CODE (WARR NCN  W-1021    0.00   115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR NCN  W-1021    0.49   115.00   56.35
ARR07 Z992      MISC LABOUR CODE (WARR NCN  W-1021    0.01   115.00    1.15
ARR07 WARR      MANUFACTURER WARRANTY JGK  W-1021    0.50   115.00   57.50
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.50   115.00   57.50
ARR07 WARR      MANUFACTURER WARRANTY JGK  W-1021    0.00   115.00    0.00
ARR08 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.50   115.00   57.50
ARR09 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.50   115.00   57.50
ARR10 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.50   115.00   57.50
ARR08 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.00   115.00    0.00
ARR09 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.00   115.00    0.00
ARR10 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.00   115.00    0.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
ARR03  FRT      FREIGHT      W-1021  1.00  91.02  91.02
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W  1021            100.32  632.50  0.00   91.02  0.00  823.84
      Totals      100.32  632.50  0.00   91.02  0.00  823.84
*****
```

&k2S
&k0S