

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10095B

Date In:	13 MAR 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11101
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	37PFL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	SOLD TO OELKE
Purchased Date:	21 APR 25	:	:
Delivery Date:	16 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUN26RP101391	:	:

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. SEAM TAPE IN I PDI PRE-D
BEDROOM LOOSE ALL OVER 2.SEAM TAPE SBOVE
DS SLIDE ON LEFT CORNER 3.STAPLE
STICKING OUT IN CELING ABOVE PANTRY
4.CHAIR MARKS/ SCUFFS ON WALL REAR OF DS
SLIDE
CAUSE: DAF concerns
CORRECTION: All issues resolved except chair Marks
from transport. Wall panel seems
damaged. Seeking management for advice
on next steps. 5/12/25 - this was
completed last year
WARR COMPLAINT: WARRANTY REPAIR 2 - Dining chairs rubbed W 1021 FORES
wall panel during transport in ds
slideout
CAUSE: Chairs rubbed during transport, ruined
two wall panels in dinette. Remove trim,
t-molding, window. Expect 6hrs to fit
and replace. Chairs rubbed wall in
dinette during transport in two spots
CORRECTION: 5/6/25 *Removed wall panels. *Removed a
ton of staples. *Taped in insulation.
*Cut ordered panels to correct
dimensions for replacement. *Refit wall
panels and trim. *Refit window
coverings. *cleanup Management needs to
advise what to do next. After some heavy
use of quik-solv, white spots still

Continued on page 2

Work Order : 10095B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
exist
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Water panel in           W    1021   FORES
        bedroom DS LOWER CABINET doesn't fit
        properly & damaged
        CAUSE:      Panel R&R per warranty
        CORRECTION: Replaced panel, cut to fit.
WARR    COMPLAINT:  WARRANTY REPAIR 4 -JUST NOTING           W    1021   FORES
        Showerhead making loud screeching noise.
        CAUSE:      ...
        CORRECTION: This was completed last year
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Bedroom DS window           W    1021   FORES
        nicked and has metal burr, center left
        side.
        CAUSE:      Damaged metal on interior of window. R&R
        per warranty.
        CORRECTION: Removed, window coverings, blind and
        valance. Removed interior mounting ring,
        cut away sealants on exterior, removed
        window. Removed excessive sealants and
        prepped for new window install.
        Installed window, trimmed sealant
        squeeze-out, finished sealing with clear
        nova-flex sealant. Reinstalled valance
        and roller shade.
WARR    COMPLAINT:  RECALL 51-1744 The Alpha Roof Sealant           W    1021   FORES
        may cause the Solar Panel Inlet to
        crack, which may allow water intrusion
        Recall
        CAUSE:
        CORRECTION: NPF, sealant is dirty, but nothing is
        cracked or leaking. Looks like alpha was
        removed already and dicor applied.
WARR    COMPLAINT:  WARRANTY REPAIR 9 - TONGUE JACK WILL           W    1021   FORES
        LOOSELY SPIN AND DOES NOT WORK AS IT
        SHOULD
        CAUSE:      Tongue jack gears are broken, won't
        function. Don't have one in stock
        currently. Waiting on parts  REQUEST 1.5
        HR
        CORRECTION: ...
WARR    COMPLAINT:  WARRANTY REPAIR 10 - THE PATIO DOOR           W    1021   FORES
        INNER FRAME HAS SOME DENTS IN THE METAL
        CAUSE:      Damaged/Bent threshold in patio doorway.
        Could probably use a transition strip
        considering the height of the lip,
        manufacturer does not use one. 35min
        CORRECTION: Used a piece of oak a c-clamp and a
        rubber mallet. Was able to straighten
        out nearly perfect.
WARR    COMPLAINT:  WARRANTY REPAIR 11 - SEAM NEAR THE           W    1021   FORES
*****
```

Continued on page 3

Work Order : 10095B

DINING ROOM TABLE IS PULLING FROM THE WALL

CAUSE: Staples in wall didn't hold, pulling seam apart.

CORRECTION: Put a couple staples in panel edge, puttied holes. Should hold better now.

```
*****
Job # Part No      Description      PARTS    Bill to    Qty    Price    Total
*****
DAF   F100347337    SEAM TAPE, 1", CLOUDED T I-PDI          0     0.15     0.00
WARR0 822037751      PANELING, LAUAN 1/8 X 48 W-1021         2    37.52    75.04
WARR0 650609         COUNTER EXTENSION BRKTS. W-1021         1    11.60    11.60
WARR0 822051708251   USERPART WATER PANEL ORD W-1021         1     9.10     9.10
WARR0 822037751      PANELING, LAUAN 1/8 X 48 W-1021         2    37.52    75.04
WARR0 019079642592  HH SHW HEAD, BK, CLASSIC W-1021         1     7.24     7.24
WARR0 20X43736A     WINDOW, 24" X 22" SV, VE W-1021         1    55.77    55.77
*****
```

```
*****
Job#  Lab Code  Description      LABOUR    Mech Bill to    Hrs    Rate    Total
*****
DAF  Z991      DAF-WARRANTY REPAIR    RW    I-PDI          0.10   70.00    7.00
DAF  Z992      MISC LABOUR CODE (WARR RW    I-PDI          0.50   70.00   35.00
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.33  115.00   37.95
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.17  115.00   19.55
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  115.00   57.50
ARR03 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.40  140.00   56.00
ARR04 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR04 WARR    MANUFACTURER WARRANTY RW    W-1021         0.50  115.00   57.50
ARR04 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  140.00   70.00
ARR07 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.00  115.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.10  115.00   11.50
ARR08 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  115.00   57.50
ARR09 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.05  115.00    5.75
ARR10 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  115.00   57.50
ARR11 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.50  115.00   57.50
ARR09 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.45  115.00   51.75
ARR07 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.40  115.00   46.00
ARR03 Z992      MISC LABOUR CODE (WARR RW    W-1021         0.10  140.00   14.00
ARR09 RV2-15a    TONGUE JACK INSTALL PO    W-1021         0.00  140.00    0.00
*****
```

```
*****
Job #  Excode    Description      EXTRAS    bill to    Qty    Price    Total
*****
DAF   FRT        FREIGHT          I-PDI          1.00   19.48   19.48
ARR02 FRT        FREIGHT & CRATE FOR PANELI W-1021         1.00  281.70  281.70
ARR07 FRT        FREIGHT          W-1021         1.00   34.03   34.03
*****
```

Continued on page 4

Work Order : 10095B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	42.00	0.00	19.48	0.00	61.48
W	1021	233.79	670.00	0.00	315.73	0.00	1,219.52
	Totals	233.79	712.00	0.00	335.21	0.00	1,281.00

&k2S
&k0S