

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10095B

Date In:	13 MAR 24	Author:	KOTT
Promised Date:	04 JUL 25	Stock No:	11101
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	37PFL
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	SOLD TO OELKE
Purchased Date:	21 APR 25	:	:
Delivery Date:	16 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUN26RP101391	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
DAF	COMPLAINT:	DAF-WARRANTY REPAIRS- 1. SEAM TAPE IN I PDI PRE-D BEDROOM LOOSE ALL OVER 2.SEAM TAPE SBOVE DS SLIDE ON LEFT CORNER 3.STAPLE STICKING OUT IN CELING ABOVE PANTRY 4.CHAIR MARKS/ SCUFFS ON WALL REAR OF DS SLIDE CAUSE: DAF concerns CORRECTION: All issues resolved except chair Marks from transport. Wall panel seems damaged. Seeking management for advice on next steps. 5/12/25 - this was completed last year		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Dining chairs rubbed W 1021 FORES wall panel during transport in ds slideout CAUSE: Chairs rubbed during transport, ruined two wall panels in dinette. Remove trim, t-molding, window. Expect 6hrs to fit and replace. Chairs rubbed wall in dinette during transport in two spots CORRECTION: 5/6/25 *Removed wall panels. *Removed a ton of staples. *Taped in insulation. *Cut ordered panels to correct dimensions for replacement. *Refit wall panels and trim. *Refit window coverings. *cleanup Management needs to advise what to do next. After some heavy use of quik-solv, white spots still		

Continued on page 2

Work Order : 10095B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                exist
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Water panel in      W    1021    FORES
                                bedroom DS LOWER CABINET doesn't fit
                                properly & damaged
                                CAUSE: Panel R&R per warranty
                                CORRECTION: Replaced panel, cut to fit.
WARR    COMPLAINT:  WARRANTY REPAIR 4 -JUST NOTING          W    1021    FORES
                                Showerhead making loud screeching noise.
                                CAUSE: ...
                                CORRECTION: This was completed last year
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Bedroom DS window   W    1021    FORES
                                nicked and has metal burr, center left
                                side.
                                CAUSE: Damaged metal on interior of window. R&R
                                per warranty.
                                CORRECTION: Removed, window coverings, blind and
                                valance. Removed interior mounting ring,
                                cut away sealants on exterior, removed
                                window. Removed excessive sealants and
                                prepped for new window install.
                                Installed window, trimmed sealant
                                squeeze-out, finished sealing with clear
                                nova-flex sealant. Reinstalled valance
                                and roller shade.
WARR    COMPLAINT:  RECALL 51-1744 The Alpha Roof Sealant    W    1021    FORES
                                may cause the Solar Panel Inlet to
                                crack, which may allow water intrusion
                                CAUSE: Recall
                                CORRECTION: NPF, sealant is dirty, but nothing is
                                cracked or leaking. Looks like alpha was
                                removed already and dicor applied.
WARR    COMPLAINT:  WARRANTY REPAIR 9 - TONGUE JACK WILL     W    1021    FORES
                                LOOSELY SPIN AND DOES NOT WORK AS IT
                                SHOULD
                                CAUSE: Tongue jack gears are broken, won't
                                function. Don't have one in stock
                                currently. Waiting on parts
                                CORRECTION: changed tounge jack
WARR    COMPLAINT:  WARRANTY REPAIR 10 - THE PATIO DOOR      W    1021    FORES
                                INNER FRAME HAS SOME DENTS IN THE METAL
                                CAUSE: Damaged/Bent threshold in patio doorway.
                                Could probably use a transition strip
                                considering the height of the lip,
                                manufacturer does not use one. 35min
                                CORRECTION: Used a piece of oak ac-clamp and a
                                rubber mallet. Was able to straighten
                                out nearly perfect.
WARR    COMPLAINT:  WARRANTY REPAIR 11 - SEAM NEAR THE       W    1021    FORES
                                DINING ROOM TABLE IS PULLING FROM THE

```

Continued on page 3

Work Order : 10095B

WALL

CAUSE: Staples in wall didn't hold, pulling seam apart.

CORRECTION: Put a couple staples in panel edge, puttied holes. Should hold better now.

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
DAF   F100347337    SEAM TAPE, 1", CLOUDED T I-PDI      0        0.15        0.00
WARR0 822037751     PANELING, LAUAN 1/8 X 48 W-1021      2       37.52       75.04
WARR0 650609        COUNTER EXTENSION BRKTS. W-1021      1       11.60       11.60
WARR0 822051708251  USERPART WATER PANEL ORD W-1021      1        9.10        9.10
WARR0 822037751     PANELING, LAUAN 1/8 X 48 W-1021      2       37.52       75.04
WARR0 019079642592  HH SHW HEAD, BK, CLASSIC W-1021      1        7.24        7.24
WARR0 20X43736A     WINDOW, 24" X 22" SV, VE W-1021      1       55.77       55.77
WARR0 002028290258  TONGUE JACK 2000 LB SIDE W-1021      1       74.44       74.44
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
DAF   Z991      DAF-WARRANTY REPAIR      RW      I-PDI      0.10      70.00        7.00
DAF   Z992      MISC LABOUR CODE (WARR RW      I-PDI      0.50      70.00       35.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.33     115.00       37.95
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.17     115.00       19.55
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR02 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     140.00       70.00
ARR03 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     115.00       57.50
ARR03 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.40     140.00       56.00
ARR04 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR04 WARR      MANUFACTURER WARRANTY      RW      W-1021      0.50     115.00       57.50
ARR04 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     140.00       70.00
ARR07 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00     115.00        0.00
ARR07 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.10     115.00       11.50
ARR08 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     115.00       57.50
ARR09 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.05     115.00        5.75
ARR10 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     115.00       57.50
ARR11 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.50     115.00       57.50
ARR09 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.45     115.00       51.75
ARR07 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.40     115.00       46.00
ARR03 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.10     140.00       14.00
ARR09 RV2-15a    TONGUE JACK INSTALL PO      W-1021      0.00     140.00        0.00
*****
```

```
*****
Job #  Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
DAF   FRT          FREIGHT          I-PDI      1.00      19.48       19.48
ARR02 FRT          FREIGHT & CRATE FOR PANELI W-1021      1.00     281.70     281.70
ARR07 FRT          FREIGHT          W-1021      1.00      34.03       34.03
*****
```

Continued on page 4

Work Order : 10095B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	42.00	0.00	19.48	0.00	61.48
W	1021	308.23	670.00	0.00	315.73	0.00	1,293.96
	Totals	308.23	712.00	0.00	335.21	0.00	1,355.44

&k2S
&k0S