

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10095B

Date In: 13 MAR 24 Author: KOTT
Promised Date: 04 JUL 25 Stock No: 11101
: Year: 2024
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: FOREST RIVER
Address: 8220 STATE HWY 13 SOUT Brand: PUMA DESTINATION
: WISCONSIN RAPIDS, WI Model: 37PFL
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: STOCK REPAIR
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 4X4TPUN26RP101391 :

Job # Description JOB INFORMATION Type Bill To

DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1. SEAM TAPE IN I PDI PRE-D
BEDROOM LOOSE ALL OVER 2.SEAM TAPE SBOVE
DS SLIDE ON LEFT CORNER 3.STAPLE
STICKING OUT IN CELING ABOVE PANTRY
4.CHAIR MARKS/ SCUFFS ON WALL REAR OF DS
SLIDE
CAUSE: DAF concerns
CORRECTION: All issues resolved except chair Marks
from transport. Wall panel seems
damaged. Seeking management for advice
on next steps.
WARR COMPLAINT: WARRANTY REPAIR 2 - Dining chairs rubbed W 1021 FORES
wall panel during transport in ds
slideout
CAUSE: Chairs rubbed during transport, ruined
two wall panels in dinette. Remove trim,
t-molding, window. Expect 6hrs to fit
and replace. Chairs rubbed wall in
dinette during transport in two spots
CORRECTION: 5/6/24 *Removed wall panels. *Removed a
ton of staples. *Taped in insulation.
*Cut ordered panels to correct
dimensions for replacement. *Refit wall
panels and trim. *Refit window
coverings. *cleanup Management needs to
advise what to do next. After some heavy
use of quik-solv, white spots still
exist REQUESTING 6 HOURS

Continued on page 2

Work Order : 10095B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Water panel in           W    1021   FORES
        bedroom DS LOWER CABINET doesn't fit
        properly & damaged
        CAUSE:      Panel damaged, incorrectly cut to size
        CORRECTION: Needs replacement, order piece of panel
        and sticker to match, see pictures
        REQUESTING 1 HOUR
WARR    COMPLAINT:  WARRANTY REPAIR 4 -JUST NOTING           W    1021   FORES
        Showerhead making loud screeching noise.
        CAUSE:      Flow restrictor in Showerhead. Removed
        Showerhead and tested ok, reattach
        shower head and noise still persists
        CORRECTION: Replaced with new Showerhead CHECKS OK
WARR    COMPLAINT:  WARRANTY REPAIR 7 - Bedroom DS window           W    1021   FORES
        nicked and has metal burr, center left
        side.
        CAUSE:      Damaged by unknown factors
        CORRECTION: Recommend replacement, poses a safety
        hazard. Window is 25 1/4" wide by 23
        1/4" tall REQUESTING 1 HOUR
WARR    COMPLAINT:  RECALL 51-1744 The Alpha Roof Sealant           W    1021   FORES
        may cause the Solar Panel Inlet to
        crack, which may allow water intrusion
        CAUSE:      MFG RECALL
WARR    COMPLAINT:  WARRANTY REPAIR 9 - TONGUE JACK WILL           W    1021   FORES
        LOOSELY SPIN AND DOES NOT WORK AS IT
        SHOULD
        CAUSE:      THE GEARS IN THE JACK WERE STRIPPED
        CAUSING IT TO NOT PERFORM ITS PROPER
        FUNCTIONS. NEED NEW JACK
        CORRECTION: REQUESTING 1 HOUR LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 10 - THE PATIO DOOR           W    1021   FORES
        INNER FRAME HAS SOME DENTS IN THE METAL
        CAUSE:      MFG
        CORRECTION: MAY NEED TO BEND BACK OR REPLACE THE
        TRACK
WARR    COMPLAINT:  WARRANTY REPAIR 11 - SEAM NEAR THE           W    1021   FORES
        DINING ROOM TABLE IS PULLING FROM THE
        WALL
        CAUSE:      NOTING FOR MFG
        CORRECTION: MAY NEED TO ADD SOME GLUE TO BRING SEAM
        BACK TO WALL
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty    Price    Total
*****
WARR0 019079642592  HH SHW HEAD, BK, CLASSIC W-1021           1      7.24     7.24
WARR0 20X43736A     WINDOW, 24" X 22" SV, VE W-1021           0     55.77     0.00
WARR0 822037751     PANELING, LAUAN 1/8 X 48 W-1021           2     37.52    75.04
    
```

Continued on page 3

Work Order : 10095B

```
*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822051708251  USERPART WATER PANEL ORD W-1021      0        9.10       0.00
WARR0 822037751     PANELING, LAUAN 1/8 X 48 W-1021      2       37.52      75.04
DAF   F100347337    SEAM TAPE, 1", CLOUDED T I-PDI      0        0.15       0.00
WARR0 650609         COUNTER EXTENSION BRKTS. W-1021      1       11.60     11.60
*****
```

```
*****
Job# Lab Code Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
DAF Z991 DAF-WARRANTY REPAIR      RW      I-PDI      0.10     70.00      7.00
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.33    115.00     37.95
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00      0.00
ARR03 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.50    115.00     57.50
ARR04 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00      0.00
ARR04 WARR MANUFACTURER WARRANTY      RW      W-1021      0.50    115.00     57.50
ARR07 Z992 MISC LABOUR CODE (WARR      W-1021      0.00    115.00      0.00
ARR07 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.10    115.00     11.50
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.17    115.00     19.55
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00      0.00
ARR02 Z992 MISC LABOUR CODE (WARR RW      W-1021      0.00    115.00      0.00
ARR08 Z992 MISC LABOUR CODE (WARR      W-1021      0.00    115.00      0.00
ARR09 Z992 MISC LABOUR CODE (WARR      W-1021      0.00    115.00      0.00
ARR10 Z992 MISC LABOUR CODE (WARR      W-1021      0.00    115.00      0.00
ARR11 Z992 MISC LABOUR CODE (WARR      W-1021      0.00    115.00      0.00
*****
```

```
*****
Job # Excode Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR07 FRT      FREIGHT      W-1021      1.00     34.03     34.03
ARR02 FRT      FREIGHT & CRATE FOR PANELI W-1021      1.00    281.70    281.70
DAF   FRT      FREIGHT      I-PDI      1.00     19.48     19.48
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I   PDI           0.00       7.00       0.00       19.48      0.00     26.48
W   1021          168.92     184.00     0.00       315.73     0.00    668.65
Totals          168.92     191.00     0.00       335.21     0.00    695.13
*****
```

&k2S
&k0S