

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10095C

Date In: 19 FEB 25 Author: MZYWICKI
Promised Date: 31 MAY 25 Stock No: 11101
: Year: 2024
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA DESTINATION
: CHICAGO, IL Model: 37PFL
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: SOLD TO OELKE
Purchased Date: 21 APR 25 :
Delivery Date: 16 MAY 25 :
InService Date: :
Serial#: 4X4TPUN26RP101391 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 2 - SEAM TAPE ABOVE W 1021 FORES
SHOWER HAS SMALL BREAK IN IT
CAUSE: Seam tape had a crease in it.
CORRECTION: Used a heat gun to warm up and flatten
back down. Looks acceptable.
WARR COMPLAINT: WARRANTY REPAIR 3 - NOTING THERE IS A W 1021 FORES
SCRATCH ON THE FREEZER DOOR
CAUSE: Scuff marks all over freezer door.
Unknown. Protective film had already
been removed. Hard to see without the
correct lighting.
CORRECTION: JUST NOTING
WARR COMPLAINT: WARRANTY REPAIR 4 - TWO OF THE BATON W 1021 FORES
STRIPS BEHIND THE COUCH ARE NOT ATTACHED
TO WALL PROPERLY
CAUSE: Batten strips behind livong room couch
in nose, popped loose, maybe during
transport.
CORRECTION: Remove couch fasteners attached to
floor. Move for access to batten strips.
Stapled strips, puttied holes,
reinstalled couch mounting brackets.
WARR COMPLAINT: WARRANTY REPAIR 5 - THE SCREEN ON THE W 1021 FORES
WINDOW BY THE DINING ROOM TABLE HAS A
BAD SEAL
CAUSE: Table not secured to floor, slid around
and rubbed screen.
CORRECTION: Replaced mesh in screen

Continued on page 2

Work Order : 10095C

```
*****
Job # Part No Description      PARTS      Bill to Qty Price Total
*****
WARR0 82207880 WINDOW, SCREEN ONLY, FOR 36" W-1021 0 32.18 0.00
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
ARR03 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
ARR04 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
ARR05 Z992 MISC LABOUR CODE (WARR RW W-1021 0.50 115.00 57.50
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1021 0.00 230.00 0.00 0.00 0.00 230.00
Totals 0.00 230.00 0.00 0.00 0.00 230.00
*****
```

&k2S
&k0S