

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497		CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2205976
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TPUN26RP101391
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	420 / 420
		ITEM #	PUT37PFL
		DEALER RO #	10095C
		CLAIM START DATE	02/19/2025
		CLAIM END DATE	05/13/2025
Labor rate:	\$115.00		
OWNER INFORMATION			
JAY OELKE			
7421 MIDLAND DRIVE			
Allenton, WI 53002			
USA			
Retail Date of Purchase	05/16/2025	WARRANTY EXPIRATION DATE	05/16/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-93-15-00-000938	Seam, per inch - Interior/Driver, Passenger Seat, Barrel Chair/Repair or Replace/ No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-02-19 16:08:15 :: Complaint: Seam tape above the shower door has a small break in it. Cause: Seam tape is creased. Correction: Need to cut and overlay with new seam tape. Additional Note : greeneway@dealer-advisors.com, 2025-02-19 16:08:40 :: No replace seam tape code			
	Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$46.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$23.00	
	Notes			
	flat rate			

Labor

Line# 2	Operation Code 70-306-01-00-001800	Operational Description Refrigerator Door - Appliances/Refrigerator (Everchill, Cannon)/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : greeneway@dealer-advisors.com, 2025-02-19 16:09:31 :: Complaint: *Noting* There is a scratch on the freezer door. Cause: From manufacturing. Correction: Noting in case future customer wants corrected.			
Model# 1	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial# 1	Appr Hrs	0.00	Appr Labor Amt	\$0.00
	Notes attach a photo of the model and serial number Photo uploaded- The dealership just noted this was the fridge door, not the freezer door. unit file noted			

Labor

Line# 3	Operation Code	Operational Description		
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2025-02-19 16:11:07 :: Complaint: Two of the baton strips behind the couch are not attached to wall properly. Cause: Staples didn't hold baton strips in place. Correction: Resecure batton strips.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$23.00
	Notes			
	flat rate to secure .10 X 2			

Labor

Line# 4

Operation Code

20-46-01-00-000726

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-02-19 16:12:57 :: Complaint: The screen on the window by the dining room table has a bad seal. Cause: Seal is starting to pull away from the frame and cause the mesh to pull away from the frame as well, creating a hole. Correction: Need to replace the screen.

Operational Description

Window Screen - Exterior/Windows/Replace/No Tread Code

Model#

Dlr Sub Hrs

0.50

Sub Labor Amt

\$57.50

Serial#

Appr Hrs

0.10

Appr Labor Amt

\$11.50

Notes

flat rate

Part Line# 1	Item #	Description
	F100157880	WINDOW, SCREEN ONLY, FOR 36" X 36" VS WINDOW, #60011
	Model #	Serial #
	Sub Qty	1.00
	Appr Qty	1.00
	Sub Dlr Price	\$32.18
	Appr Dlr Price	\$32.18
	Part tag	
	Sub Freight	\$18.31
	Appr Freight	\$18.31
	Notes	

Submitted	Labor Amt	\$161.00	Approved	Labor Amt	\$57.50
	Parts & Freight	\$50.49		Parts & Freight	\$50.49
	Total	\$211.49		Total	\$107.99

DEALER

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

DATE

CUSTOMER

SIGNATURE

All repairs described have been inspected and are satisfactory.

DATE