

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10106B

Date In: 07 MAR 24 Author: KOTT  
Promised Date: 04 JUL 24 Stock No: 11013  
: Year: 2024  
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN  
Address: 8220 STATE HWY 13 SOUT Brand: IMAGINE AIM  
: WISCONSIN RAPIDS, WI Model: 16BL  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): 800-758-2272 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#:  
Purchased Date: :  
Delivery Date: :  
InService Date: :  
Serial#: 573TE201XR7702021 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
DAF	COMPLAINT: DAF-WARRANTY REPAIRS- 1. BRACKET OUT OF I ALIGNMENT, CAUSED DAMAGE TO SCREEN AND ENTRANCE DOOR. 2. TRIM PIECE LOOSE IN BAGGAGE COMPARTMENT ds front 3. UPPER SINK CABINET DOOR WARPED 4.MURPHY BED FRONT RIGHT CORNER IS BENT		PDI	PRE-D
	CORRECTION: LOOKED AT DAF REPAIRS AND MADE LINES FOR ONES NEEDING REPAIR			
WARR	COMPLAINT: The step latch caused damage to screen and entry door		W	1020 GRAND
	CAUSE: Entry door catch caused damage to screen NEED .3 FOR REPAIR			
	CORRECTION: Per shawn take off the one door latch cuz the door only opens so far cause the awning arm is right there I moved the latch as far as I could but it was still hitting the door so shawn told me to just take the latch off			
WARR	COMPLAINT: Upper sink cabinet door warped		W	1020 GRAND
	CAUSE: Cabinet door warped NEED .6 FOR REMOVAL AND REPLACEMENT.			
	CORRECTION: Got new cabinet door from parts took old door off to line up Handel and latches had to use the jig the new door doesn't come with the holes in it so we had to drill them out and then reinstall the door			
WARR	COMPLAINT: Murphy bed corner bed latch is bent		W	1020 GRAND

Continued on page 2

Work Order : 10106B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
CAUSE:   Murphy bed front corner bed latch is
          bent NEED .3 FOR REPAIR
CORRECTION: Bed latch was not bent just had to
          remove two screws and mount the latch
          flush and put the two screws back into
          the latch
WARR    COMPLAINT: Trim piece is loose is storage           W    1020    GRAND
          compartment
CAUSE:   Trim piece popped up in front storage
          compartment NEED .2 FOR REPAIR
CORRECTION: Used Brad nailer and nailed back in
          place
WARR    COMPLAINT: Low flow out of shower hose in bathroom W    1020    GRAND
CAUSE:   Low water flow out of bathroom shower
          NEED .3 FOR REPAIR
CORRECTION: The hose for the shower has two small of
          a hole to keep up with the pump so I put
          on a different hose and is fine this is
          the 2nd camper this has happened to
WARR    COMPLAINT: Missing remote for tv                   W    1020    GRAND
CAUSE:   Tv remote missing from camper
CORRECTION: Parts order new tv remote got new remote
          and took out to the lot and put in
          camper

```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WARR0 82202773    DOOR CABINET 15MM X 1/2 W-1020    1    46.70   46.70
WARR0 019079642578 HH SHW HOSE BK, 59, VINY W-1020    1     6.85    6.85
WARR0 822040287    TV Remote           W-1020    1    60.13   60.13

```

```

*****
Job# Lab Code Description   LABOUR   Mech Bill to   Hrs   Rate   Total
*****
DAF Z991 DAF-WARRANTY REPAIR   CF   I-PDI   0.10   70.00   7.00
ARR01 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR02 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR02 WARR MANUFACTURER WARRANTY CF W-1020 0.50 115.00 57.50
ARR03 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR04 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR05 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR06 Z992 MISC LABOUR CODE (WARR CF W-1020 0.50 115.00 57.50
ARR06 WARR MANUFACTURER WARRANTY CF W-1020 0.50 115.00 57.50

```

```

*****
Job # Excode Description   EXTRAS   bill to   Qty   Price   Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00

```

Continued on page 3

Work Order : 10106B

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty   Price   Total
*****
ARR02  FRT        FREIGHT                W-1020    1.00   13.75   13.75
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I   PDI            0.00     7.00     0.00     0.00     0.00     7.00
W   1020          113.68   460.00    0.00    13.75     0.00   587.43

      Totals      113.68   467.00    0.00    13.75     0.00   594.43
*****
```

&k2S  
&k0S