

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10106B

Date In:	07 MAR 24	Author:	KOTT
Promised Date:	04 JUL 24	Stock No:	11013
:	:	Year:	2024
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	IMAGINE AIM
:	WISCONSIN RAPIDS, WI	Model:	16BL
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TE201XR7702021	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
DAF     COMPLAINT:  DAF-WARRANTY REPAIRS-  1. BRACKET OUT OF I    PDI    PRE-D
          ALIGNMENT, CAUSED DAMAGE TO SCREEN AND
          ENTRANCE DOOR. 2. TRIM PIECE LOOSE IN
          BAGGAGE COMPARTMENT ds front 3. UPPER
          SINK CABINET DOOR WARPED 4.MURPHY BED
          FRONT RIGHT CORNER IS BENT
          CORRECTION: LOOKED AT DAF REPAIRS AND MADE LINES FOR
          ONES NEEDING REPAIR
WARR    COMPLAINT:  The step latch caused damage to screen    W    1020    GRAND
          and entry door
          CAUSE:      Entry door catch caused damage to screen
          NEED .3 FOR REPAIR
          CORRECTION: Per shawn take off the one door latch
          cuz the door only opens so far cause the
          awining arm is right there I moved the
          latch as far as I could but it was still
          hitting the door so shawn told me to
          just take the latch off
WARR    COMPLAINT:  Upper sink cabinet door warped            W    1020    GRAND
          CAUSE:      Cabinet door warped NEED .6 FOR REMOVAL
          AND REPLACEMENT.
          CORRECTION: Got new cabinet door from parts took old
          door off to line up Handel and latches
          had to use the jig the new door doesn't
          come with the holes in it so we had to
          drill them out and then reinstall the
          door
WARR    COMPLAINT:  Murphy bed corner bed latch is bent        W    1020    GRAND
```

Continued on page 2

Work Order : 10106B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      Murphy bed front corner bed latch is
                  bent NEED .3 FOR REPAIR
      CORRECTION: Bed latch was not bent just had to
                  remove two screws and mount the latch
                  flush and put the two screws back into
                  the latch
WARR    COMPLAINT: Trim piece is loose is storage           W      1020    GRAND
                  compartment
      CAUSE:      Trim piece popped up in front storage
                  compartment NEED .2 FOR REPAIR
      CORRECTION: Used Brad nailer and nailed back in
                  place
WARR    COMPLAINT: Low flow out of shower hose in bathroom W      1020    GRAND
      CAUSE:      Low water flow out of bathroom shower
                  NEED .3 FOR REPAIR
      CORRECTION: The hose for the shower has two small of
                  a hole to keep up with the pump so I put
                  on a different hose and is fine this is
                  the 2nd camper this has happened to
WARR    COMPLAINT: Missing remote for tv                     W      1020    GRAND
      CAUSE:      Tv remote missing from camper
      CORRECTION: Parts order new tv remote got new remote
                  and took out to the lot and put in
                  camper

```

```

*****
Job # Part No   Description   PARTS   Bill to   Qty   Price   Total
*****
WARR0 82202773   DOOR CABINET 15MM X 1/2 W-1020     1    46.70   46.70
WARR0 019079642578 HH SHW HOSE BK, 59, VINY W-1020     1     6.85    6.85
WARR0 822040287   TV Remote           W-1020     1    60.13   60.13

```

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to   Hrs   Rate   Total
*****
   DAF Z991      DAF-WARRANTY REPAIR   CF   I-PDI      0.10   70.00    7.00
ARR01 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.50  115.00   57.50
ARR02 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.08  115.00    9.20
ARR02 WARR      MANUFACTURER WARRANTY   CF   W-1020    0.50  115.00   57.50
ARR03 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.50  115.00   57.50
ARR04 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.50  115.00   57.50
ARR05 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.50  115.00   57.50
ARR06 Z992      MISC LABOUR CODE (WARR CF   W-1020    0.00  115.00    0.00
ARR06 WARR      MANUFACTURER WARRANTY   CF   W-1020    0.20  115.00   23.00

```

```

*****
Job #  Excode   Description   EXTRAS   bill to   Qty   Price   Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL W-1020    1.00    0.00    0.00

```

Continued on page 3

Work Order : 10106B

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR02  FRT      FREIGHT           W-1020     1.00    13.75    13.75
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id           Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PDI              0.00      7.00      0.00      0.00      0.00      7.00
W      1020             113.68    319.70     0.00     13.75      0.00     447.13

      Totals           113.68    326.70     0.00     13.75      0.00     454.13

```

&k2S
&k0S