

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10107B

Date In:	02 APR 24	Author:	DLUCAS
Promised Date:	31 DEC 25	Stock No:	11066
:	:	Year:	2024
Customer Name:	88870 - BINKOWSKI, ROG	Manufacturer:	CROSSROADS
Address:	6202 CANOE STREET	Brand:	HAMPTON
:	WESTON, WI	Model:	378DBB
Postal/Zip:	54476	Miles/Hrs:	0
Phone#(res):	715-571-3809	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	715-340-5330	License#:	
Email:	PEPPY 17@CHARTER.NET	Tag#:	
Purchased Date:	29 MAR 24	:	:
Delivery Date:	02 MAY 24	:	:
InService Date:		:	:
Serial#:	4YDTHPT26R9330243	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
DAF     COMPLAINT:  DAF-WARRANTY REPAIRS-  1. SCRATCH IN          I    PDI    PRE-D
        UPPER SLIDE ROOM TRIM ABOVE TABLE 2.
        PATIO VALANCE OFF & LAYING ON FLOOR IN
        FRONT OF PATIO DOOR
        CAUSE:      Trim above slide out has a small scratch
                    per shawn just noting it the valance
                    that fell off matt and jess put back up
                    when it was checked in
        CORRECTION: Done
WARR    COMPLAINT:  Lp leak                      W    1047    CROSS
        CAUSE:      Lp leak
        CORRECTION: Were the rubber line meets the steel
                    line Were the brass or copper fitting is
                    was leaking lp tightened the fitting and
                    preformed a time drop test and held at 8
                    inches of water for 3 minutes
WARR    COMPLAINT:  Bathroom door has nicks and scratches in W    1047    CROSS
        it
        CAUSE:      Door has scratches and nicks in it need
                    to order new door Door has scratches
                    and nicks in it need to order new door
        CORRECTION: ...remove the damage bathroom door
                    measurements taken and transfer hinges
                    and door handle onto new door and re
                    attached to framework and tested ok ...
WARR    COMPLAINT:  Cabinet door in bedroom has scratches    W    1047    CROSS
        and is missing a screw
        CAUSE:      Need new cabinet door has scratches in
```

Continued on page 2

Work Order : 10107B

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
                                it from factory  needed new cabinet
                                handle with screws
CORRECTION: ...  remove and install the new cabinet
                                handle to door with screws now ok
WARR    COMPLAINT: Sliding door in bedroom has scratches  W    1047    CROSS
                                and was covered with putty from factory
                                but still needs to be replaced
CAUSE:    Sliding door in bedroom has scratches
                                and nicks in it and was covered up with
                                putty from factory need new door Sliding
                                door in bedroom has scratches and nicks
                                in it and was covered up with putty from
                                factory need new door
CORRECTION: ...removel of upper Wood trim  to gain
                                excess to hinges disconnected the slide
                                door bracket measurements taken transfer
                                the hinges onto new door and re attached
                                hinges the door is now working ...
1        COMPLAINT: CUSTOMER STATES THAT UNDERNEATH THE BED  W    1047    CROSS
                                IN THE REAR OF THE UNIT- THERE IS A
                                COMPARTMENT DOOR ON THE EXTERIOR OF THE
                                UNIT THAT ALLOWS ACCESS TO THE AREA-
                                WHEN IT RAINS THERE IS WATER GETTING IN
                                AND SOAKING THE GENERAL VACINITY-
CAUSE:    Couldn't diagnose the leak possible
                                customer had not close properly and it
                                is raining today and no leaks
CORRECTION: customer will keep a eye on it
2        COMPLAINT: CUSTOMER STATES THAT IN THE MAIN BATH      W    1047    CROSS
                                DIRECTLY BY THE PATIO DOOR- THE VALVE
                                THAT KEEPS THE WATER IN THE TOILET BOWL
                                DOES NOT CLOSE ALL THE WAY ALLOWING THE
                                WATER TO SEEP OUT-
CAUSE:    pics taken I found that the ball valve
                                for flushing is getting stuck will need
                                a new toilet
CORRECTION: install the ball valve kit and tested
                                the toilet is working and holding water
3        COMPLAINT: CUSTOMER STATES THAT WHEN YOU TURN ON      W    1047    CROSS
                                THE LIGHTS FOR THE STOVE ALL OF THE
                                LIGHTS COME ON EXCEPT FOR ONE OF THE
                                TURN KNOBS-
CAUSE:    the left rear burner knob assembly the
                                light iis not working pics taken this is
                                a sealed stove so idkif replacement of
                                complete knob with light assembly or
                                replacing the complete stove
CORRECTION: replacing complete stove or the complete
                                know assembly with light tried

```

Continued on page 3

Work Order : 10107B

installing lights onto knob for stove
 was the wrong ones these lights was
 three wires i needed two wire lights
 they was hard wired in not plug and play
 either new lights or complete stove the
 new stove had arrived i remove and
 installed the new cooking stove i also
 tested all components and tested for
 leaks the oven is now working

4 CUSTOMER REQUESTS SERVICE CALL TO THEIR UNIT VISTA E 88870 BINKO
 ROYALLE CAMPGROUND SITE# 137

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WARR0	822093725	Passage - Door - 1 3/8" x	W-1047	1	151.71	151.71	
WARR0	822093725	Passage - Door - 1 3/8" x	W-1047	1	151.71	151.71	
WARR0	822095061	Cabinet - Door - FPSQ - 12	W-1047	1	24.67	24.67	
WARR0	628061	Door - Pull - 128MM - Matt	W-1047	6	1.70	10.20	
2	42209	KIT WB DA STYLE II AMR	W-1047	1	24.03	24.03	
3	2022451535	BURNER KNOB LIGHTS	W-1047	5	4.67	23.35	
3	822022011	Range - 24" - Greystone -	W-1047	1	1,875.50	1,875.50	
3	82205457	LED PCB LAMP #28	W-1047	0	7.98	0.00	

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
DAF	Z991	DAF-WARRANTY REPAIR	CF	I-PDI	0.10	70.00	7.00	
ARR01	Z992	MISC LABOUR CODE (WARR	CF	W-1047	0.32	105.00	33.60	
ARR01	Z992	MISC LABOUR CODE (WARR	CF	W-1047	0.18	105.00	18.90	
ARR02	Z992	MISC LABOUR CODE (WARR	CF	W-1047	0.50	105.00	52.50	
ARR03	Z992	MISC LABOUR CODE (WARR	CF	W-1047	0.50	105.00	52.50	
ARR04	Z992	MISC LABOUR CODE (WARR	CF	W-1047	0.50	105.00	52.50	
3	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	105.00	52.50	
2	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	105.00	52.50	
1	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.49	105.00	51.45	
ARR02	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	105.00	52.50	
ARR03	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	105.00	52.50	
ARR04	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	105.00	52.50	
1	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.01	105.00	1.05	
2	W320	TOILET, R & R	JS	W-1047	0.50	105.00	52.50	
3	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.00	140.00	0.00	
2	W320	TOILET, R & R	JS	W-1047	1.00	140.00	140.00	
3	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	140.00	70.00	
3	WARR	MANUFACTURER WARRANTY	JS	W-1047	0.50	140.00	70.00	

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
ARR01	SSE	SHOP SUPPLIES - EXTERNAL	W-1047	1.00	0.00	0.00	
ARR04	FRT	CRATE FEE	W-1047	1.00	50.00	50.00	
ARR03	FRT	FREIGHT FOR JOB WARR03 CAB	W-1047	0.00	0.00	0.00	

Continued on page 4

Work Order : 10107B

```

*****
Job #  Excode   Description   EXTRAS      bill to      Qty      Price      Total
*****
ARR04  FRT       FREIGHT FOR PASSAGE DOORS  W-1047      1.00     175.27     175.27
ARR02  FRT       FREIGHT FOR DOOR PULLS JOB W-1047      1.00      22.81      22.81
   3  FRT       FREIGHT                W-1047      1.00      10.00      10.00
   4  SC       SERVICE CALL           E-88870     20.00       3.75      75.00
   3  FRT       FREIGHTFOR JOB 3 LED LAMP W-1047      1.00      20.64      20.64
   3  FRT       FREIGHT                W-1047      0.00       0.00       0.00
*****

```

```

*****
                        BILLINGS SUMMARY
*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      88870         0.00        0.00        0.00       75.00      4.13      79.13
I      PDI          0.00        7.00        0.00        0.00      0.00       7.00
W      1047        2261.17     857.50        0.00      278.72      0.00     3,397.39

      Totals        2261.17     864.50        0.00     353.72      4.13     3,483.52

```

&k2S
&k0S