

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10107B

Date In:	02 APR 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11066
:	:	Year:	2024
Customer Name:	1047 - CROSSROADS RV	Manufacturer:	CROSSROADS
Address:	1115 WEST LAKE ST	Brand:	HAMPTON
:	TOPEKA, IN	Model:	378DBB
Postal/Zip:	46571	Miles/Hrs:	0
Phone#(res):	260-593-3850	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	29 MAR 24	:	:
Delivery Date:	02 MAY 24	:	:
InService Date:	:	:	:
Serial#:	4YDTHPT26R9330243	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
DAF     COMPLAINT:  DAF-WARRANTY REPAIRS-  1. SCRATCH IN          I    PDI    PRE-D
        UPPER SLIDE ROOM TRIM ABOVE TABLE 2.
        PATIO VALANCE OFF & LAYING ON FLOOR IN
        FRONT OF PATIO DOOR
        CAUSE:      Trim above slide out has a small scratch
                     per shawn just noting it the valance
                     that fell off matt and jess put back up
                     when it was checked in
        CORRECTION: Done
WARR    COMPLAINT:  Lp leak                      W    1047    CROSS
        CAUSE:      Lp leak
        CORRECTION: Were the rubber line meets the steel
                     line Were the brass or copper fitting is
                     was leaking lp tightened the fitting and
                     preformed a time drop test and held at 8
                     inches of water for 3 minutes
WARR    COMPLAINT:  Bathroom door has nicks and scratches in W    1047    CROSS
        it
        CAUSE:      Door has scratches and nicks in it need
                     to order new door Door has scratches
                     and nicks in it need to order new door
        CORRECTION: ...remove the damage bathroom door
                     measurements taken and transfer hinges
                     and door handle onto new door and re
                     attached to framework and tested ok ...
WARR    COMPLAINT:  Cabinet door in bedroom has scratches    W    1047    CROSS
        and is missing a screw
        CAUSE:      Need new cabinet door has scratches in
```

Continued on page 2

Work Order : 10107B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
          it from factory  needed new cabinet
          handle with screws
CORRECTION: ...  remove and install the new cabinet
          handle to door with screws now ok
WARR    COMPLAINT: Sliding door in bedroom has scratches  W    1047    CROSS
          and was covered with putty from factory
          but still needs to be replaced
CAUSE:    Sliding door in bedroom has scratches
          and nicks in it and was covered up with
          putty from factory need new door Sliding
          door in bedroom has scratches and nicks
          in it and was covered up with putty from
          factory need new door
CORRECTION: ...removel of upper Wood trim  to gain
          excess to hinges disconnected the slide
          door bracket measurements taken transfer
          the hinges onto new door and re attached
          hinges the door is now working ...
1        COMPLAINT: CUSTOMER STATES THAT UNDERNEATH THE BED  W    1047    CROSS
          IN THE REAR OF THE UNIT- THERE IS A
          COMPARTMENT DOOR ON THE EXTERIOR OF THE
          UNIT THAT ALLOWS ACCESS TO THE AREA-
          WHEN IT RAINS THERE IS WATER GETTING IN
          AND SOAKING THE GENERAL VACINITY-
CAUSE:    Couldn't diagnose the leak possible
          customer had not close properly and it
          is raining today and no leaks
CORRECTION: customer will keep a eye on it
2        COMPLAINT: CUSTOMER STATES THAT IN THE MAIN BATH      W    1047    CROSS
          DIRECTLY BY THE PATIO DOOR- THE VALVE
          THAT KEEPS THE WATER IN THE TOILET BOWL
          DOES NOT CLOSE ALL THE WAY ALLOWING THE
          WATER TO SEEP OUT-
CAUSE:    pics taken I found that the ball valve
          for flushing is getting stuck will need
          a new toilet
CORRECTION: Will need a new toilet.... REQUEST  1.5
          HOURS LABOR  AND NEW TOILET
3        COMPLAINT: CUSTOMER STATES THAT WHEN YOU TURN ON      W    1047    CROSS
          THE LIGHTS FOR THE STOVE ALL OF THE
          LIGHTS COME ON EXCEPT FOR ONE OF THE
          TURN KNOBS-
CAUSE:    the left rear burner knob assembly the
          light iis not working pics taken this is
          a sealed stove so idkif replacement of
          complete knob with light assembly or
          replacing the complete stove
CORRECTION: replacing complete stove or the complete
          know assembly with light ..... REQUEST:

```

Continued on page 3

Work Order : 10107B

1.5HOURS LABOR AND NEW OVEN

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
WARR0 822093725 Passage - Door - 1 3/8" x 2 W-1047 1 151.71 151.71
WARR0 822093725 Passage - Door - 1 3/8" x 2 W-1047 1 151.71 151.71
WARR0 822095061 Cabinet - Door - FPSQ - 12" W-1047 1 24.67 24.67
WARR0 628061 Door - Pull - 128MM - Matte W-1047 6 1.70 10.20
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
DAF Z991 DAF-WARRANTY REPAIR CF I-PDI 0.10 70.00 7.00
ARR01 Z992 MISC LABOUR CODE (WARR CF W-1047 0.32 105.00 33.60
ARR01 Z992 MISC LABOUR CODE (WARR CF W-1047 0.18 105.00 18.90
ARR02 Z992 MISC LABOUR CODE (WARR CF W-1047 0.50 105.00 52.50
ARR03 Z992 MISC LABOUR CODE (WARR CF W-1047 0.50 105.00 52.50
ARR04 Z992 MISC LABOUR CODE (WARR CF W-1047 0.50 105.00 52.50
3 WARR MANUFACTURER WARRANTY JS W-1047 0.50 105.00 52.50
2 WARR MANUFACTURER WARRANTY JS W-1047 0.50 105.00 52.50
1 WARR MANUFACTURER WARRANTY JS W-1047 0.49 105.00 51.45
ARR02 WARR MANUFACTURER WARRANTY JS W-1047 0.50 105.00 52.50
ARR03 WARR MANUFACTURER WARRANTY JS W-1047 0.50 105.00 52.50
ARR04 WARR . JS W-1047 0.50 105.00 52.50
1 WARR MANUFACTURER WARRANTY JS W-1047 0.01 105.00 1.05
2 W320 TOILET, R & R W-1047 0.00 105.00 0.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1047 1.00 0.00 0.00
ARR04 FRT CRATE FEE W-1047 1.00 50.00 50.00
ARR03 FRT FREIGHT FOR JOB WARR03 CAB W-1047 0.00 0.00 0.00
ARR04 FRT FREIGHT FOR PASSAGE DOORS W-1047 1.00 175.27 175.27
ARR02 FRT FREIGHT FOR DOOR PULLS JOB W-1047 1.00 22.81 22.81
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I PDI 0.00 7.00 0.00 0.00 0.00 7.00
W 1047 338.29 525.00 0.00 248.08 0.00 1,111.37

Totals 338.29 532.00 0.00 248.08 0.00 1,118.37
*****
```

&k2S

&k0S