



8:59:13 AM

Last Modified By

Component Serial Number 501 1/18/2024

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	6107706B	Toilet - Thetford - Blade Seal	1.5	1.5	210	0	1	1	Approved
	Complaint	Customer states that in the main bath, directly by the patio door- the valve that keeps the water in the toilet bowl does not close all the way allowing the water to seep out.			Notes ROGER & VICKI BINKOWSKI				
	Cause	The ball valve for flushing is getting stuck.			210				
	Correction	R&R toilet. (Not sure if this is the correct labor code?)							
		KRV VCB waste ball drive arm kit part number 42209, at 1.50 of labor							



Claim CLAIM42606 (C3885860) Last Modified By

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4147406B	Oven - Furrion - Replace Complete	0.5	0.5	70	0	1	0.5	Approved
Complaint Customer states that when you turn on the lights for the stove, all of the lights come on except for one of the turn knobs. Cause The left rear burner knob assembly the light is not working. This is a sealed stove so we don't know if replacement of complete knob with light assembly or replacing the complete stove. Correction Replace complete stove or the complete knob assembly with light - need manufacturer guidance. *unsure on labor code as I don't see a Greystone brand. KRV-5-30-2025 UPdate, part is NLA, Approved to replace complete *KRV VCB This is pre-auth for the R&R of the PCB LED 2022451535. We will approve up to .20 for labor. KRV-VCB cost to vendor									

Submitted parts & subLet	1,923.57	Approved parts & subLet	1,904.89
Submitted labor & subLet	280.00	Approved labor & subLet	280.00
Submitted freight	279.93	Approved freight	290.57
Total Submitted	<u>2,483.50</u>	Total approved	<u>2,475.46</u>