

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10114B

Date In:	05 MAR 24	Author:	TPASSER
Promised Date:	25 DEC 24	Stock No:	11085
:	:	Year:	2022
Customer Name:	1620 - MAGUIRE, SCOTT	Manufacturer:	FOREST RIVER
Address:	8311 STATE HWY 13 S	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	38RLB
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	715-712-0430	Exterior Color:	:
Phone#(bus):	715-459-7185	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	:	Tag#:	:
Purchased Date:	30 JAN 24	:	:
Delivery Date:	09 MAR 24	:	:
InService Date:	:	:	:
Serial#:	4X4TPUP20NP096986	:	:

Job # Description JOB INFORMATION Type Bill To

DAF DAF-WARRANTY REPAIRS- 1.ODS - FRONT & REAR S/O &DS I PDI PRE-D
S/O - SILICONE NEEDS TO BE CLEANED OF TRIM 2. PATIO
DOOR CURTAIN ROD COMING OUT 3.BR - MIRRORED DOORS
NOT PROPERTY FINISHED LEFT DOOR SCUFF IN WOOD BY
HANDLE 4. STAPLES VISIBLE AROUND WALL 5.REFER
TILTED TO ONE SIDE 6.DISCOLORING ON THE LEFT CUSHION
(IF SITTING ON COUCH)
WARR COMPLAINT: WARRANTY REPAIR 1 - patio door curtain W 1021 FORES
rod coming out of the wall
CAUSE: Screws had no anchors to hold such a
heavy bar WILL NEED .50 FOR REPAIR
CORRECTION: Removed the one screw left on each side
then drilled out a bit more then put 4
anchors in and had Dustin hold the rod
while I reinstalled the curtain rod
WARR COMPLAINT: WARRANTY REPAIR 2 - kitchen sink has W 1021 FORES
gaps in the sealant around the top of
sink
CAUSE: Silicone shrank and was leaving gaps
around top of kitchen sink WILL NEED .40
FOR REPAIR
CORRECTION: Cleaned well the used leftover clear
silicone to seal
WARR COMPLAINT: WARRANTY REPAIR 3 -dsfront top screw W 1021 FORES
has backed away from unit
CAUSE: Screw came loose over time WILL NEED .10
FOR REPAIR.
CORRECTION: Screwed back into place

Continued on page 2

Work Order : 10114B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 4 -batten tape loose      W    1021    FORES
          throughout the unit
          CAUSE:      Loose tape
          CORRECTION: Pressed into place
WARR    COMPLAINT:  WARRANTY REPAIR 5 -side of bed has a      W    1021    FORES
          crack in the panel no Integrity issue
          with this
          CAUSE:      Cracked on delivery. PLEASE ORDER 16
          1/4" wide x 78" long wood grain panel
          and 4 batten strips and 2 outside corner
          in same color of wood grain as panel
          pics attached
          CORRECTION: ..... CUSTOMER HAS NO
          RECOLECTION OF THIS CONCERN NEEDING TO
          BE DONE- STOCK PARTS AND CLOSE WORK
          ORDER
WARR    COMPLAINT:  WARRANTY REPAIR 6 -loose corner trim in   W    1021    FORES
          the main bedroom to the left of door
          CAUSE:      Loose trim
          CORRECTION: Used pin nailer to secure
WARR    COMPLAINT:  WARRANTY REPAIR 7 -the bedrooms entrance W    1021    FORES
          to outside you can see light between the
          wall and frame
          CAUSE:      Not sealed between door frame and wall.
          WILL NEED .20 FOR REPAIR
          CORRECTION: I used black silicone to seal the gap
WARR    COMPLAINT:  WARRANTY REPAIR 8 -the table is not       W    1021    FORES
          screwed down
          CAUSE:      Mfg never screwed table down. WILL
          NEED.30 FOR REPAIR.
          CORRECTION: Installed 4 screws and I also put
          bumpers on panel that the table touches
          when slide out is in
WARR    COMPLAINT:  WARRANTY REPAIR 9 - be bottom of bed      W    1021    FORES
          door is peeling up
          CAUSE:      Peeling bottom edge of door from mfg
          this way. WILL NEED .20 FOR REPAIR.
          CORRECTION: Used dab of glue to resecure
WARR    COMPLAINT:  WARRANTY REPAIR 10 -carpet against wall   W    1021    FORES
          behind dining table is bare in a spot
          CAUSE:      Improper install cut too short. WILL
          NEED .20 FOR REPAIR.
          CORRECTION: Used a knife to fluff up the carpet
          fibers and pressed the carpet backing
          down looks more full and bare areas not
          as visible
WARR    COMPLAINT:  WARRANTY REPAIR 11 - ONLY NOTING THE      W    1021    FORES
          BUNK SLIDE ROOF BENEATH RUBBER ROOF
          LOOKS LIKE THE WOOD IS PUCKETED THERE IS

```

Continued on page 3

Work Order : 10114B

NO ISSUE WITH LEAKING OR INTEGRITY JUST
NOTING IF IN FUTURE CUSTOMER HAS A
QUESTION WITH THIS

CAUSE: Please note with mfg

CORRECTION: Please note with mfg

WARR COMPLAINT: WARRANTY REPAIR 12 -ONLY NOTING THE W 1021 FORES
INTERIOR SLIDE LEGS ON UNIT DO NOT LOOK
TO BE FULLY WRAPPED I AM NOTING IN CASE
FUTURE ISSUE.

CAUSE: Mfg built this way Talk with Shawn and
he approved to note this

CORRECTION: Please note with mfg

Job # Part No Description PARTS Bill to Qty Price Total

WARR0 F100185296 PANELING, 2.7MM X 48" X 96 W-1021 0 55.16 0.00
WARR0 822085309 MOLDING, BATTEN, #198, 1.5 W-1021 0 3.09 0.00
WARR0 822085317 MOLDING, OUTSIDE CORNER, # W-1021 0 15.30 0.00

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DAF Z991 DAF-WARRANTY REPAIR I-PDI 0.00 70.00 0.00
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.13 115.00 14.95
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.37 115.00 42.55
ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.43 115.00 49.45
ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.07 115.00 8.05
ARR06 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR07 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.49 115.00 56.35
ARR07 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.01 115.00 1.15
ARR08 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.47 115.00 54.05
ARR08 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.03 115.00 3.45
ARR09 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.37 115.00 42.55
ARR09 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.13 115.00 14.95
ARR10 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR11 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50
ARR12 Z992 MISC LABOUR CODE (WARR HOD W-1021 0.50 115.00 57.50

BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total

W 1021 0.00 690.00 0.00 0.00 0.00 690.00
Totals 0.00 690.00 0.00 0.00 0.00 690.00

Continued on page 4

Work Order : 10114B

&k2S
&k0S