



Warranty Claim Form

Date: 7/10/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR2827N3343419
Reflection 226RK
Retail Purchase Date: 2/24/2024
Work Started: 3/4/2024
Work Completed: 3/4/2024

Claim Status: Paid
Dealer Work Order #: 10130B
Unit Offline Date: 5/17/2022

Claim #: 815592
Labor: \$103.50
Parts: \$173.69
Shipping: \$28.04
Total: \$305.23

Notes: Please advise on line 3. Are you only claiming 1 of part # 661763 or did you mean to claim 2? If 2, please adjust the quantity to reflect. :) NN 7.2 zd 3/18

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

DAVID PILLER
2411 JEFFEREY LANE
SCHOFIELD, Wisconsin 54476
United States
715-297-0669

Operation Line # 1

Flat Rate Code: 660001 Cabinet Doors - R&R Door *Fault Code:* Improper Installation/Build

Problem: Cabinet door above bed has a crack on interior bottom *Hours:* .3
Cause: Came from mfg with crack Please order a 20 wide x 12 tall cabinet door *Amount:* 34.50
Remedy: REPLACE *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
661786 DOOR CABINET 20 x 12 BROWNSTONE MAPLE ADORN RRPSQ	DOOR CABINET 20 x 12 BROWNSTONE MAPLE ADORN RRPSQ		1	1	39.55

Operation Line # 2

Flat Rate Code: 660001 Cabinet Doors - R&R Door *Fault Code:* Improper Installation/Build

Problem: the cabinet door on bottom of dining bench closest to door is cracked *Hours:* .3
Cause: Cracked from mfg Please order 18 1/4 wide x 10 1/4 tall *Amount:* 34.50
Remedy: REPLACE *Sublet Repairs:* \$0.00

Manufacturer #: *Model #:* *Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
661783 DOOR CABINET 18 1/4 x 10 3/8 BROWNSTONE MAPLE ADORN RRPSQ	DOOR CABINET 18 1/4 x 10 3/8 BROWNSTONE MAPLE ADORN RRPSQ		1	1	33.34

Operation Line # 3

Flat Rate Code: 660001 Cabinet Doors - R&R Door

Fault Code: Improper Installation/Build

Problem: ohc near bench both doors cracked

Hours: .3

Cause: Please order 2 cabinet doors 10 wide x 32 long pics attached

Amount: 34.50

Remedy: REPLACE

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
661763 DOOR CABINET 10 x 32 BROWNSTONE MAPLE ADORN RRPSQ	DOOR CABINET 10 x 32 BROWNSTONE MAPLE ADORN RRPSQ		2	1	100.80