

Claim Response

Claim: C3667885

Last Modified byMcCoS

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3667885	10136B	6/5/2024	7/19/2024	4YDTHPU23R9330277	PA03656878	1612	Greeneway Inc 8220 State Hwy 13 S Wisconsin Rapids, WI 54494	140.00	0.00	WARR	

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	732003	Shade - Roller - Night Only - 4	1.00	1.00	169.77	15.00	195.24	25.96	25.96	0.00	Approved

INV 4711258

Component Model: Component Serial Number: P501 2/6/24

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3300506B	Blind - Vertical - Replace Complaint: Motorized shade in bedroom is not working. Goes a few inches and stops Cause: Bad power motor Correction: Will need a new motorized window shade. KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)	STOCK	0.50	0.50	70.00	0.00	1	0.50	Approved

Submitted parts & subLet 195.24
Submitted labor & subLet 70.00
Submitted freight: 25.96
Tax: 0.00
Total Submitted: 291.20

Approved parts & subLet 195.24
Approved labor & subLet 70.00
Approved freight: 25.96
Tax: 0.00
Total approved: 291.20