



Warranty Claim Form

Date: 6/6/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3421R3347614
Reflection 295RL
Retail Purchase Date: 8/14/2023
Work Started: 5/13/2024
Work Completed: 5/13/2024

Claim Status: Paid
Dealer Work Order #: 10176
Unit Offline Date: 7/27/2023

Claim #: 806763
Labor: \$115.00
Parts: \$0.00
Shipping: \$0.00
Total: \$115.00

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

GARY GAUTHIER
3304 CUMBERLAND AVE
STURGEON BAY, Wisconsin 54235
United States
920-559-2703

Operation Line # 1

Flat Rate Code: 620004 Floor Covering - Repair Linoleum (per *Fault Code:* Improper Installation/Build sq. yd.)

Problem: There is something under the flooring in the bedroom. Customer believes it is a screw.
*Unsure on labor code.

Hours: 1

Cause: Manufacturer flaw. Something is trapped in the floor under the linoleum.

Amount: 115.00

Remedy: Pulled trim, pulled staples, Found a foreign piece of plastic trapped in the flooring, reapplied trim, applied putty in the staple holes.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: