



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

[spreading the joy of the camping lifestyle]

(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com

W/O: 10180B
Promised Date:



WO #: 10180B

Customer Name: 1000 - GREENEWAY RV
SALES & SERVICE

Address: 8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS, WI

Postal/Zip: 54494

Phone#(res): 800-758-2272

Phone#(bus):

Cell Phone:

Email: NONE

Date In: 18 MAR 24

Promised Date: 04 JUL 24

Purchased Date:

Delivery Date:

InService Date:

Serial#: 573TE3224R6649625

Author: MGRAY

Stock No: 11127

Year: 2024

Manufacturer: GRAND DESIGN

Brand: IMAGINE

Model: 2800BH

Miles/Hrs: 0

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#:

Job #WARR01 - Warranty

COMPLAINT: WARRANTY REPAIR 1 - the units shore cord has a cut in it

CAUSE: Deep Cut / Gouge in Shore cord

CORRECTION: Replaced shore cord in unit with new warranty replacement, tested OK

Labor

Job #	Description	Total
WARR01	MULTIPLE LABOR CODES	57.50

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES - EXTERNAL	1.00	0.00	0.00
FRT	FREIGHT	1.00	14.14	14.14

Subtotal for Job #WARR01: 71.64

Job #WARR03 - Warranty

COMPLAINT: WARRANTY REPAIR 3 -Drawer beneath the bed has sharp splintered edges

CAUSE: Slivered edges on drawer from mfg this way

CORRECTION: Used sand paper and removed sharp shards off corners of drawer

Labor

Job #	Description	Total
WARR03	MISC LABOUR CODE (WARRANTY)	23.00

Subtotal for Job #WARR03: 23.00

Job #WARR02 - Warranty

COMPLAINT: WARRANTY REPAIR 2 - ODS light above the bed the screw in lens/ light refractor has a deep line in the end of it

CAUSE: Defective Light fixture, requires replacement per warranty

CORRECTION: Replaced ODS reading light fixture in bedroom

Labor

Job #	Description	Total
WARR02	MULTIPLE LABOR CODES	50.60

Customer #: 1000
GREENEWAY RV SALES &
SERVICE



W/O: 10180B
Promised Date: 04 JUL 24

Parts	Description	Qty	Price	Total
Part # 822020899	LIGHT INTERIOR 12V FLEXIBLE READING LIGHT BLACK WARM WHITE 3000K	1.00	15.13	15.13

Other Services	Description	Qty	Price	Total
Code FRT	FREIGHT	1.00	12.44	12.44
FRT	FREIGHT	1.00	12.44	12.44

Subtotal for Job #WARR02: 90.61

Job #WARR04 - Warranty

COMPLAINT: WARRANTY REPAIR 4 - bedroom sliding door glide came off.

CAUSE: Mfg left it loose

CORRECTION: Removed door fascia above sliding door then reinserted the tab on door into the glued hardware tested works reinstalled fascia

Labor	Description	Total
Job # WARR04	MISC LABOUR CODE (WARRANTY)	34.50

Subtotal for Job #WARR04: 34.50

Parts Total: 15.13
Labour Total: 165.60
Sublet Total: 0.00
Extras Total: 39.02
WORK ORDER TOTAL: 219.75

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : _____

Date: 14 May 2024



Customer #: 1000
GREENEWAY RV SALES &
SERVICE,

