

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10218B

Date In: 08 AUG 24 Author: AFREEMAN
Promised Date: 25 DEC 24 Stock No: 10908
: Year: 2023
Customer Name: 16458 - MULVANEY, MICH Manufacturer: GRAND DESIGN
Address: 1426 RAINDANCE TRAIL, Brand: REFLECTION FW
: NEKOOSA, WI Model: 337RLS
Postal/Zip: 54457 Miles/Hrs:
Phone#(res): 414-333-0850 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: KATHLEEN.MULVANEY@OUTL Tag#:
Purchased Date: 29 JUL 23 :
Delivery Date: 05 AUG 23 :
InService Date: :
Serial#: 573FR3724P9924075 :

Job #	Description	JOB INFORMATION	Type	Bill To
4	COMPLAINT: CUSTOMER STATES THAT THE DS AND ODS PROPANE COMPARTMENT DOORS SEEM LOOSE- CUSTOMER STATES THAT THEY COME OPEN IN TRAVEL- CAUSE: The bottom latch on the ds and the top latch on the ods are to short. I got longer ones and I had to change the shape of them a little bit to get the doors to latch properly. NEED .50 FOR REPAIRS. CORRECTION: Custom shaped new longer latches. installed them and doors now latch properly.		W	1020 GRAND
5	COMPLAINT: CUSTOMER STATES THAT THE DINETTE TABLE IS LOOSE- CAUSE: The table base is loose. I took the four screws out, flipped the table over and tightened down the nut that's on the bottom. I put the four screws back in and their was still a slight wobble so I added a few nails to the post. need .50 for repairs. CORRECTION: needed to remove table top to resecure the bracket securing top to the base, it was still wobbly so I added a few nails to secure it better then reinstalled the tapletop.		W	1020 GRAND
7	COMPLAINT: CUSTOMER STATES THAT THE MARKER LIGHT ON W		W	1020 GRAND

Continued on page 2

Work Order : 10218B

Job #	Description	JOB INFORMATION	Type	Bill To
-------	-------------	-----------------	------	---------

THE ODS OF THE FRONT CAP IS BURNT OUT
AND NEEDS TO BE REPLACED- POSSIBLE BAD
GROUND

CAUSE: A combination of the manufacturer over
tightening the screws causing the case
to crack and they're strands of wiring
sticking out around the wire connector
that are touching the aluminum frame. I
cut the silicone, removed the screws and
the light fell apart. As I was trying to
get the wire connectors out, I saw a
couple of sparks, and after I got the
connectors out, I saw strands of a wire
hanging out. We don't have the light, so
I had to get one ordered. I installed
and tested the new light.need .50 for
repairs.

CORRECTION: removed light, tested it not working.
reinstalled a new light tested it
working correctly.

8	COMPLAINT:	CUSTOMER STATES THAT THE AUTO LEVEL KEEPS THROWING A CODE THAT TELLS HIM TO OPERATE MANUALLY- SAME CODE THAT IT WAS SAYING PREVIOUSLY- SAME CODE THAT WAS PREVIOUSLY-	W	1020	GRAND
---	------------	---	---	------	-------

CAUSE: Faulty controller. I turned the system
on, and it had a code for the front
right jack. I extended all the legs six
inches and retracted them all. I ran the
front jacks up and down and I noticed
the the front ds jack is always lagging
behind. I extended and retracted them
all four times and the jack would always
lag. I checked to make sure that the leg
is getting proper voltage and it is. I
went to switch the plugs on the
controller for the front jacks to verify
if it's a leg or controller issue and
the plug that's attached to the board
isn't attached all the way. The soder
welds broke so I replaced the board. I
re calibrated the auto level system and
auto leveled and retracted the system
several times to test it with no issues.
will need 3.5 hrs for all testing and
repairs and a new one control board
ordered.

CORRECTION: will need a new one control board
installed.

Continued on page 3

Work Order : 10218B

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
4 822060727 DOOR BAGGAGE BD CAM FINGER W-1020 2 2.50 5.00
7 822020997 LIGHT LED AMBER MARKER SIDE W-1020 1 6.01 6.01
8 82203280 LCI 4 PT.ONE CONTROL JACK L W-1020 1 583.62 583.62
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
4 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 115.00 57.50
4 WARR MANUFACTURER WARRANTY JGK W-1020 0.00 115.00 0.00
5 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 115.00 57.50
7 WARR MANUFACTURER WARRANTY JGK W-1020 0.21 115.00 24.15
7 WARR MANUFACTURER WARRANTY JGK W-1020 0.00 115.00 0.00
7 WARR MANUFACTURER WARRANTY JGK W-1020 0.29 115.00 33.35
8 Z990 MISC LABOUR CODE (EXTE JGK W-1020 0.00 115.00 0.00
8 Z990 MISC LABOUR CODE (EXTE JGK W-1020 0.81 115.00 93.15
8 Z990 MISC LABOUR CODE (EXTE JGK W-1020 0.19 115.00 21.85
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
7 FRT FREIGHT W-1020 1.00 12.48 12.48
*****
```

```
*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1020 594.63 287.50 0.00 12.48 0.00 894.61
Totals 594.63 287.50 0.00 12.48 0.00 894.61
*****
```

&k2S
&k0S