

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10264

Date In: 05 APR 24 Author: MGRAY
Promised Date: 15 APR 24 Stock No: 11016
: Year: 2024
Customer Name: 9490 - DENNY, CORNELIU Manufacturer: GRAND DESIGN
Address: 3381 ROYAL OAK DR Brand: IMAGINE XLS
: PLOVER, WI Model: 22MLE
Postal/Zip: 54467 Miles/Hrs:
Phone#(res): 715-498-3704 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: 715-498-3705 License#:
Email: DENNYNJ@CHARTER.NET Tag#:
Purchased Date: 04 DEC 23 :
Delivery Date: 08 DEC 23 :
InService Date: :
Serial#: 573TE2622R3437263 :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: SHOWER DOOR IS LOOSE. THERE IS A W 1020 GRAND
PLASTIC/ACRYLIC PIECE THAT IS NOT
ATTACHED AS IT SHOULD BE.
CAUSE: Loose shower door hardware
CORRECTION: Tightened screw on top of shower track.
No longer loose. Operating as it should.
2 COMPLAINT: WEATHER STRIPPING ON BOTTOM OF SCREEN W 1020 GRAND
DOOR IS NOT MAKING SEAL. YOU CAN SEE
STRAIGHT OUTSIDE, INSTEAD OF SEALING.
CAUSE: Customer states door not sealing on
bottom. Confirmed by pictures. Door
sweep is not contacting threshold on
both sides of door. Sweep has a
permanent bend to it. Needs to be
replaced to correct the problem.
POSSIBLE SCREEN DOOR REPLACEMENT OR
REPLACE SWEEP ONLY
CORRECTION: ...
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF E 9490 DENNY
REPAIR IS NEEDED.
CAUSE: Customer requests roof inspection
CORRECTION: Roof inspection performed, nothing
unusual or obvious going on with roof.
Sealant looks adequate and membrane is
fully intact.
3 CMR STATES THAT THE SWAY BARS WERE HARD TO GET E 9490 DENNY
LATCHED, NOT SURE THAT IF THE BARS ARE JUST STIFF OR

Continued on page 2

Work Order : 10264

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
      SOMETHING IS WRONG WILL HAVE TO BE SHOWN AT TIME OF
      HOOK UP
4      COMPLAINT:  CMR HAS NOT TAKEN UNIT OUT FOR ANY TRIP, E      9490    DENNY
      PULLED FROM HERE HOME AND BACK HERE.
      CHECK OVER FOR ANYTHING CMR MAY HAVE
      MISSED FOR WARRANTY.
      CORRECTION: NOTHING NOTICED WHILE WORKING ON IT
5      CODE FOR DOOR 2886                                          E      9490    DENNY

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   1  Z992      MISC LABOUR CODE (WARR RW    W-1020    0.50   115.00   57.50
   2  WARR      MANUFACTURER WARRANTY RW    W-1020    0.50   115.00   57.50
RI  Z991      PREFORM ROOF INSPECTIO RW    E-9490    0.30   105.00   31.50
   3  Z990      MISC LABOUR CODE (EXTE      E-9490    0.00   105.00    0.00

```

```

*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
   2   SSE      SHOP SUPPLIES - EXTERNAL    W-1020    1.00    2.36    2.36

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
E    9490          0.00     31.50     0.00     0.00     1.74     33.24
W    1020          0.00    115.00     0.00     2.36     0.00    117.36

      Totals        0.00    146.50     0.00     2.36     1.74    150.60

```

&k2S
&k0S