



Warranty Claim Form

Date: 7/18/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2622R3437263
Imagine 22MLE
Retail Purchase Date: 12/8/2023
Work Started: 6/14/2024
Work Completed: 6/14/2024

Claim Status: Paid
Dealer Work Order #: 10264
Unit Offline Date: 11/13/2023

Claim #: 818437
Labor: \$57.50
Parts: \$65.21
Shipping: \$12.44
Total: \$135.15

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

CORNELIUS I DENNY
3381 ROYAL OAK DR
PLOVER, Wisconsin 54467
United States
715-498-3704

Operation Line # 1

Flat Rate Code: 350042 Showers - Door Adjustments

Fault Code: Improper Installation/Build

Problem: Shower door is loose.

Hours: .3

Cause: Plastic/Acrylic piece is not attached as it should be. Hardware is loose.

Amount: 34.50

Remedy: Tightened the screw on the top of the shower track.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 560015 Entry Door - Adjust Screen Door

Fault Code: Improper Installation/Build

Problem: Weather stripping on the bottom of the screen door is not making seal. You can see outside.

Hours: .2

Cause: Door sweep is not contacting the threshold. Sweep has a permanent bend to it.

Amount: 23.00

Remedy: R & R sweep, possible screen door replacement.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag</u> <u>#</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
561325 DOOR ENTRANCE SEAL .50 X 1.00 X 250 FT BRUSH PILE	DOOR ENTRANCE SEAL .50 X 1.00 X 250 FT BRUSH PILE (BOTTOM SWEEP)		12	5	65.21