

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10273

Date In:	06 APR 24	Author:	MGRAY
Promised Date:	06 APR 25	Stock No:	
:		Year:	2024
Customer Name:	17285 - ZUEHLKE, GREG	Manufacturer:	GRAND DESIGN
Address:	3665 GOLDEN EAGLE DR	Brand:	REFLECTION
:	BELOIT, WI	Model:	370FLS
Postal/Zip:	53511	Miles/Hrs:	
Phone#(res):	6084499498	Exterior Color:	
Phone#(bus):	608-449-9649	Unit Type:	FW-FIFTH WHEEL
Cell Phone:		License#:	
Email:	TTIME4TWO@MSN.COM	Tag#:	CALLED W/ UPDATE. POO
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	573FR4327R9925493	:	

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
AS      COMPLAINT:  ANNUAL STORAGE                                E    17285  ZUEHL
        CAUSE:      NEED STORE
        CORRECTION:  STORED
WS      COMPLAINT:  WINTERIZE WATER SYSTEM & TRAPS -SELF        E    17285  ZUEHL
        CONTAINED - TOWABLE
        CAUSE:      NEED WINTERIZE
        CORRECTION:  WINTERIZED BY KEVIN, CODY, JESS
1      COMPLAINT:  CUSTOMER STATES THAT ONE OF THE TIRES ON W    1020  GRAND
        THE DOOR SIDE OF THE UNIT- THE BEARING
        BUDDY CAME OFF AND NEEDS TO BE PUT BACK
        ON
        CAUSE:      3/4/25 - Retrieved from storage for
                     service work. Request repair bearing
                     buddy on DS. Decided to check them all
                     and noticed one on ODS side is also
                     floating around in the hub too. A known
                     flaw on these axles when they switched
                     to aluminum bearing buddies. Recommend
                     removing all the aluminum Bearing
                     buddies/dust caps and replacing them
                     with the steel ones that stay in place.
                     (30min per hub x4)
        CORRECTION:  R&R bearing buddies/dust caps with steel
                     ones from AP products. Tightened Lugnuts
                     to manufacturer specifications. Good to
                     go.
2      COMPLAINT:  CUSTOMER STATES THAT THE FRONT DOOR          W    1020  GRAND
        SEEMS LIKE IT IS OUT OF SQUARE- CUSTOMER
```

Continued on page 2

Work Order : 10273

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
                STATES THAT YOU HAVE TO SLAM IT REALLY
                HARD IN ORDER TO GET IT TO CLOSE-
    CAUSE:    The front door seems really hard to
                close
    CORRECTION: Looking at the door and opening the door
                multiple times. The striker plate moved
                a little bit i just unscrewed the plate
                and moved it back over and tightened the
                screws back up door closes just fine now

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WS      071247312003 -50 ANTIFREEZE/ 1 GALLON E-17285      3      10.69      32.07
1       711217012525 DUST CAP LUBED F/7K & 8K W-1020      2      7.94      15.88

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
WS W495      WINTERIZE RV (WATER SY      E-17285      0.00      140.00      0.00
1 WARR      MANUFACTURER WARRANTY      RW      W-1020      2.00      115.00      230.00
2 WARR      MANUFACTURER WARRANTY      W-1020      0.00      115.00      0.00
2 WARR      MANUFACTURER WARRANTY      CF      W-1020      0.20      115.00      23.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
AS AS      ANNUAL STORAGE      E-17285      1.00      402.00      402.00
AS SSE      SHOP SUPPLIES - EXTERNAL      E-17285      1.00      0.00      0.00
WS J-ADJ      QUOTE ADJUSTMENT      E-17285      1.00      72.93      72.93
1 FRT      FREIGHT      W-1020      1.00      13.45      13.45

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E      17285      32.07      0.00      0.00      474.93      27.91      534.91
W      1020      15.88      253.00      0.00      13.45      0.00      282.33

Totals      47.95      253.00      0.00      488.38      27.91      817.24

```

&k2S
&k0S