



Warranty Claim Form

Date: 5/8/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE3024R6650860
Imagine 2500RL
Retail Purchase Date: null
Work Started: 4/29/2024
Work Completed: 4/29/2024

Claim Status: Paid
Dealer Work Order #: 10307B
Unit Offline Date: 3/26/2024

Claim #: 798413
Labor: \$149.50
Parts: \$0.00
Shipping: \$0.00
Total: \$149.50

Notes: JS 04/29/24 650002 (updated code) 170010 (updated code)

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Operation Line # 1

Flat Rate Code: 650002 Base Cabinets - Repair *Base Fault Code:* Improper Installation/Build Cabinet

Problem: Sharp staple protruding from cubby in the bathroom. *Not sure on correct labor code

Hours: .3

Cause: Staple was not installed all the of way and was very sharp.

Amount: 34.50

Remedy: Used a small set of cutters to remove the staple.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 710020 Ducting - Repair Roof AC Ducting/ *Fault Code:* Improper Installation/Build Plenum

Problem: AC ceiling vent in the bathroom is rattling. Something is loose in the duct.

Hours: .5

Cause: Piece of plastic is flapping inside the vent.

Amount: 57.50

Remedy: Removed the ceiling vent and cut the plastic away.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 170010 Lippert Electric - R&R Head *Fault Code:* Improper Installation/Build Assembly

Problem: The slide room lip is rubbing on linoleum when slide out comes in.

Hours: .5

Cause: There is a lot of debris beneath the slideroom lip getting drug across the fllow when closing the slideroom and there was a chunk of tape on left underside of slideroom. *Amount:* 57.50

Remedy: Vacuumed up the debris from under the slide lip and tried wiping exterior underside of the floor *Sublet Repairs:* but it is not dirty. Pulled the chunk of sticky tape from under left side floor. We suggest putting a slide ski \$0.00 that goes on interior floor for slide to go on top of.

Manufacturer #:

Model #:

Serial #: