

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10364B

Date In: 09 JUL 24 Author: MGRAY
Promised Date: 04 JUL 24 Stock No: 11139
: Year: 2024
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: REFLECTION 150 SERIES
: WISCONSIN RAPIDS, WI Model: 270BN
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FR3129R3349888 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 2 - The shade behind the W 1020 GRAND
recliner retracts really fast.
CAUSE: 1000 DEFECT FROM MANUFACTURER. I
adjusted the tension on the shade. TOOK
.30 FOR REPAIR
CORRECTION: Shade now works as it should.
WARR COMPLAINT: WARRANTY REPAIR 3 - The auto-level needs W 1020 GRAND
to be re calibrated.
CAUSE: 1000 DEFECT FROM MANUFACTURER. I re
calibrated the auto-level system. took
.30 for repair
CORRECTION: Calibrated and working as it should.
WARR COMPLAINT: WARRANTY REPAIR 4 - When the table turns W 1020 GRAND
into a bed, it doesn't rest on the edges
of the bench seat.
CAUSE: I had Matt look at it, and he doesn't
think it's supposed to be a bed.
CORRECTION: no repair needed.
WARR COMPLAINT: WARRANTY REPAIR 7 - Their are marks in W 1020 GRAND
the vynel in front of the recliners and
table.
CAUSE: 1000 DEFECT FROM MANUFACTURER. I
cleaned them off with quick-solve and a
rag. took .20 for clean up and repair.
CORRECTION: marks in vinyl are removed.
WARR COMPLAINT: WARRANTY REPAIR 8 - Their are no weep W 1020 GRAND
holes in the underbelly.
CAUSE: The manufacturer has told us before that

Continued on page 2

Work Order : 10364B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                their should be weep holes in the
                                underbelly to prevent the underbelly
                                from dropping out in case of a water
                                leak. I used my utility knife to make
                                small cuts in the underbelly about every
                                four feet. took .30 for repair.
WARR    CORRECTION:  There are now weep holes in underbelly.
COMPLAINT:  WARRANTY REPAIR 9 - Their are small      W    1020   GRAND
                                dents and scratches in the ods cargo
                                door frame.
CAUSE:      1000 DEFECT FROM MANUFACTURER. The dents
                                are slight so I just touched up the
                                paint with a marker. took .10 for repair
WARR    CORRECTION:  dents and scratches are covered.
COMPLAINT:  WARRANTY REPAIR 10 - The ds outdoor     W    1020   GRAND
                                kitchen door frame has a large scuff
                                mark.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I covered
                                the scuff mark with a black paint pen.
                                took .20 for repairs
WARR    CORRECTION:  scuff mark is now covered.
COMPLAINT:  WARRANTY REPAIR 12 - The sealant is     W    1020   GRAND
                                cracked on the ds front bottom corner.
CAUSE:      1000 DEFECT FROM MANUFACTURER. I cleaned
                                off the old sealant and re sealed it.
                                took .20 for repair
CORRECTION: sealant cleaned and reapplied.

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR02 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR02 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR03 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR03 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR04 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR04 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR07 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR07 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR08 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR08 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR09 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR09 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR10 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR10 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00
ARR12 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.50  115.00  57.50
ARR12 Z992    MISC LABOUR CODE (WARR JGK W-1020  0.00  115.00   0.00

```

Continued on page 3

Work Order : 10364B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	0.00	460.00	0.00	0.00	0.00	460.00
	Totals	0.00	460.00	0.00	0.00	0.00	460.00

&k2S
&k0S