



8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494

(715) 325-5170  
mail@greenewayrv.com  
www.greenewayrv.com

[ spreading the joy of the camping lifestyle ]

W/O: 10412  
Promised Date:  
no MAY 24



Customer #: 16716  
BURLETON, GEORGE



WO #: 10412 (Appointment Date: 01 MAY 2024 - Time: 01:00pm)

Customer Name: 16716 - BURLETON,  
GEORGE

Address: 5179 W Century Farm Blvd  
Appleton, WI

Postal/Zip: 54913

Phone#(res): 9207342039

Phone#(bus):

Cell Phone:

Email: gburleton@new.rr.com

Date In: 01 MAY 24

Promised Date: 08 MAY 24

Purchased Date: 22 NOV 22

Delivery Date: 17 MAY 23

InService Date:

Serial#: 573TE3027P5510062

Author: KOTT

Stock No: 10540

Year: 2023

Manufacturer: GRAND DESIGN

Brand: IMAGINE

Model: 2600RB

Miles/Hrs:

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#: JESSE

#### Job #WARR01 - Warranty

COMPLAINT: WARRANTY REPAIR 1 - CUSTOMER STATES THAT THE HANGING BARN DOORS IN THE UNIT THAT GO TO THE BEDROOM/BATHROOM ARE HUNG CROOKED- CUSTOMER STATES THAT THE DOORS RUB- WOULD LIKE TO HAVE LOOKED AT GAP BETWEEN DOOR AND WALL IN BATHROOM AND BEDROOM SLIDE DOORS.

CAUSE: The partial wall going into the bedroom is warped. I adjusted the door so it was even, but their is still a gap in the middle, and now the top edge of the door is visible. After i fixed the trim on the door jam the door is flush when open.

To fix the wall I will have to remove the door, the track the door sits in, the decorative pieces that hide the track and the plastic trim. After all that's removed I will have to shim the wall out with paneling and put it all back together. The job could take 2-3 hours depending on how poorly it's constructed.

I adjusted the bathroom door until it was flush when closed and fixed the door jam trim.

CORRECTION: ...

REQUEST 3 HOURS OF LABOR

#### Labor

| Job #  | Description                 | Total |
|--------|-----------------------------|-------|
| WARR01 | MISC LABOUR CODE (WARRANTY) | 57.50 |

**Subtotal for Job #WARR01: 57.50**

#### Job #WARR02 - Warranty

COMPLAINT: WARRANTY REPAIR 2 - CUSTOMER STATES THAT THE CURTAINS IN THE BEDROOM ARE HUNG CROOKED- CUSTOMER WOULD LIKE TO HAVE THEM STRAIGHTENED OUT- WHEN CURTIAN IS PULLED DOWN, THERE IS A GAP THAT LIGHT COMES IN IN BEDROOM DOOR SIDE CURTAIN

CAUSE: The shade was a little off center.

I straightened it out.

The job took .2 to complete

CORRECTION: Done.

#### Labor

| Job #  | Description                 | Total |
|--------|-----------------------------|-------|
| WARR02 | MISC LABOUR CODE (WARRANTY) | 57.50 |



Subtotal for Job #WARR02: 57.50

**Job #WARR03 - Warranty**

COMPLAINT: WARRANTY REPAIR 3 - CUSTOMER STATES THAT THE REFER WHEN RUNNING HAS A VERY LOUD "OPERATING NOISE" ALMOST LIKE A VIBRATION OR A RATTLE/HUMMING - WOULD LIKE TO HAVE DIAGNOSED/LOOKED AT- CMR STATES IT IS LOUD ENOUGH TO KEEP YOU UP AT NIGHT.

CAUSE: The furrion refrigerators are an absolute terrible appliance and they all make make noise but this one is extremely loud to the point that's all you hear while your in the unit. The vibration is coming from underneath the refrigerator. We need to know what the manufacturer wants done about it.

CORRECTION: ...  
NEED GUIDANCE FROM WARRANTY AS FAR AS HOW THEY WOULD LIKE TO PROCEED- REFER IS EXCESSIVELY NOISEY-

| Labor                     |                             |       |
|---------------------------|-----------------------------|-------|
| Job #                     | Description                 | Total |
| WARR03                    | MISC LABOUR CODE (WARRANTY) | 57.50 |
| Subtotal for Job #WARR03: |                             | 57.50 |

**Job #WARR04 - Warranty**

COMPLAINT: WARRANTY REPAIR 4 - BATHROOM WINDOW IS LEAKING FROM TOP OF THE WINDOW DOWN. CMR IS WIPING UNDER UNIT TO PREVENT WATER DAMAGE.

CAUSE: NPF.  
I didn't see anything obviously wrong with the outside of the window, but I cleaned the area and sealed around it. After the sealant dried, I sprayed it with water, went inside, and checked the window, and the top of the window frame was pretty dusty, and I didn't see any water leak.  
I need more information.

CORRECTION: ...

| Labor                     |                             |       |
|---------------------------|-----------------------------|-------|
| Job #                     | Description                 | Total |
| WARR04                    | MISC LABOUR CODE (WARRANTY) | 57.50 |
| Subtotal for Job #WARR04: |                             | 57.50 |

**Job #WARR05 - Warranty**

COMPLAINT: WARRANTY REPAIR 5 - WINDOWS ON THE SLIDE OUT SIDE ARE LEAKING. LEAKING FROM TOP LIKE BATHROOM WINDOWS, BUT NOT AS HEAVILY. NOT WINDOWS ON THE SIDE OF SLIDE OUT, WINDOWS ON THE EXTERIOR OF THE SLIDEOUT.

\*\*\*CMR added that the leak happened when the rain was very heavy and blowing back towards the rear of the unit. \*\*\*

CAUSE: NPF.  
I inspected both of the windows, and the sealant looks good. I sprayed both windows multiple times with a hose and went inside, and everything was dry with no evidence of any water getting in. The windows weren't closed all the way so I don't know if this is the reason the customers seen water or not.

CORRECTION: Done

| Labor                     |                             |       |
|---------------------------|-----------------------------|-------|
| Job #                     | Description                 | Total |
| WARR05                    | MISC LABOUR CODE (WARRANTY) | 57.50 |
| Subtotal for Job #WARR05: |                             | 57.50 |

**Job #WARR06 - Warranty**

COMPLAINT: WARRANTY REPAIR 6 - TRIM AROUND BATHROOM AND BEDROOM IS LOOSE AND COMING OFF.

W/O: 10412  
Promised Date: 08 MAY 24



Customer #: 16716  
BURLETON, GEORGE





CAUSE: The manufacturer used one small bead of silicone along the whole length of each of the door jams to whole the trim on.  
 I peeled all four of them off, cut the silicone off, loosened the bottom door holder brackets, put multiple strips of 3m tape on the back side of the trim, stuck all of them on and tightened down the door brackets. I didn't fix the one in the bedroom with the warped wall. That repair will be on another line.

CORRECTION: Done

| Labor                     |                             |       |
|---------------------------|-----------------------------|-------|
| Job #                     | Description                 | Total |
| WARR06                    | MISC LABOUR CODE (WARRANTY) | 57.50 |
| Subtotal for Job #WARR06: |                             | 57.50 |

#### Job #SUM - External

COMPLAINT: SUMMERIZE CAMPER AND DEWINTERIZE

CAUSE: 1001 CUSTOMER REQUESTED  
 Done.

CORRECTION: Done.  
 Quoted Amount: 55.00

| Labor                  |                          |      |       |       |
|------------------------|--------------------------|------|-------|-------|
| Job #                  | Description              |      |       | Total |
| SUM                    | SUMMERIZE                |      |       | N/C   |
| Other Services         |                          |      |       |       |
| Code                   | Description              | Qty  | Price | Total |
| SSE                    | SHOP SUPPLIES - EXTERNAL | 1.00 | N/C   | N/C   |
| J-ADJ                  | QUOTE ADJUSTMENT         | 0.00 | N/C   | N/C   |
| Subtotal for Job #SUM: |                          |      |       | 0.00  |

#### Job #RI - Internal

COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF REPAIR IS NEEDED.

CAUSE: Everything looks good.

CORRECTION: Done.

| Labor                 |                         |       |
|-----------------------|-------------------------|-------|
| Job #                 | Description             | Total |
| RI                    | PREFORM ROOF INSPECTION | N/C   |
| Subtotal for Job #RI: |                         | 0.00  |

#### Job #1 - External

CHECK TIRE PRESSURE, TIRE WEAR, AND ANY OTHER CONCERNS. `

| Parts                |                           |      |       |       |
|----------------------|---------------------------|------|-------|-------|
| Part #               | Description               | Qty  | Price | Total |
| 014717116305         | 2pk WATER HEATER DRAIN PL | 1.00 | N/C   | N/C   |
| Subtotal for Job #1: |                           |      |       | 0.00  |



W/O: 10412  
Promised Date: 08 MAY 24

|                          |               |
|--------------------------|---------------|
| Parts Total:             | 0.00          |
| Labour Total:            | 345.00        |
| Sublet Total:            | 0.00          |
| Extras Total:            | 0.00          |
| <b>WORK ORDER TOTAL:</b> | <b>345.00</b> |

**CUSTOMERS CLEAR RECEIPT**

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.  
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : \_\_\_\_\_

Date: 07 May 2024



Customer #: 16716  
BURLETON, GEORGE

