

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10516

Date In: 21 MAY 24 Author: MGRAY
Promised Date: 28 MAY 24 Stock No: 11096
: Year: 2023
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA TT
: CHICAGO, IL Model: 24FBSC
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: db 5/23 - updated cmr
Purchased Date: 04 MAR 24 :
Delivery Date: 12 MAR 24 :
InService Date: :
Serial#: 5ZT2PUNB7P4018079 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: AFTER ADDITIONAL SEAL PLACE, IN HARD W 1021 FORES
LARGE AMOUNT OF STILL LEAKING.
RECOMMENDING WIDE GUTTER WITH SPOUTS ON
UNIT. WATER IS BUILDING UP TO FAST
CAUSING LEAK TO CONTINUE INTO INTERIOR
OF UNIT. GUTTER WITH SPOUT WILL PREVENT
BUILD-UP OF WATER CAUSING LEAK AND SPOUT
WILL DETER EXSESSIVE AMOUNTS OF WATER
FROM RUNNING DOWN UNIT. ** FR states
"per the photos i would like the tech to
R/R THE EXTERIOR FASIA AND CORNER BLOCKS
TO CURRENT ONES THE FLAT RATE IS 3 HOURS
PLEASE CONFIRM THESE REPAIRS SO I CAN
AUTHORIZE CLAIM ??"
CAUSE: Water leaking into unit after a heavy
rain at the top of slide seal ods.
CORRECTION: Had to reseal the top of the dseal area
to prevent water getting behind the
mounting strip. Tested good.

Job # Part No Description PARTS Bill to Qty Price Total

WARR 82200111 TRIM METAL 16' ET INSERT GU W-1021 0 66.01 0.00
WARR 822000364 GUTTER SPOUT LONG L&R BLACK W-1021 0 1.87 0.00

Continued on page 2

Work Order : 10516

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
WARR RV30G-3  MOLDING R&R FLAT\ /CORN TD  W-1021  3.00  115.00  345.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1021 0.00 345.00 0.00 0.00 0.00 345.00
Totals 0.00 345.00 0.00 0.00 0.00 345.00
*****
```

&k2S
&k0S