

GREENEWAY, INC.  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS WI  
 US  
 54494  
 (715) 325-5170

WORK ORDER # 10559

Date In: 28 MAY 24 Author: TPASSER  
 Promised Date: 07 JUN 24 Stock No:  
 : Year: 2023  
 Customer Name: 90065 - LAHR, KENNETH Manufacturer: SOLITUDE  
 Address: 2089 CHARLES STREET Brand: SOLITUDE  
 : DE PERE, WI Model: 391DL  
 Postal/Zip: 54115 Miles/Hrs: 0  
 Phone#(res): 920-321-6734 Exterior Color:  
 Phone#(bus): Unit Type:  
 Cell Phone: License#:  
 Email: KENNYKK63@YAHOO.COM Tag#: db 6/14  
 Purchased Date: :  
 Delivery Date: :  
 InService Date: :  
 Serial#: 573FS4421PAA14335 :

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
SC      SERVICE CALL TO CASTLEROCK - RUSTIC RIDGE RESORT      E    90065  LAHR
WARR    COMPLAINT:  REAR SLIDEOUT IS LEAKING AT CORNER-      W    1020  GRAND
        LEAVING PUDDLE AT BASE OF SLIDEOUT.
        SCHWINTEK SLIDEOUT
        CAUSE:      on off door side rear bedroom slide
        water tested the slide out and with
        garden hose I also checked leveling is
        ok and other water lines I can't find no
        leaks at this time customer will keep
        eye on it
        CORRECTION: found no leaks at this time
WARR    COMPLAINT:  RECLINER IN UNIT IS MAKING A "CLUNKING" W    1020  GRAND
        SOUND WHEN OPERATING
        CAUSE:      standing in front of sofa recliner on
        right hand side ot sitting in sofa the
        left hand side sofa is popping and
        catching as you recline what I found was
        the framework under sofa is bent causing
        the clunking noise will need a new sofa
        pics taken
        CORRECTION: Will need a new sofa.....
WARR    COMPLAINT:  CMR REPORTS BLACK AND GREY TANK HANDLES W    1020  GRAND
        APPEAR TO BE REVERSED IN REAR TANKS -
        WOULD LIKE JS TO CHECK - CMR REPORTS HE
        IS GETTING STUFF OUT OF BOTH BUT WANTS
        LOOKED AT.
        CAUSE:      it seems to me that the rear shower the
        toilet and bathroom sink is plumb into
  
```

Continued on page 2

Work Order : 10559

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                one tank is that normal may have to call
                                grand design to get answers f before
                                lowering underbelly to look into to see
                                how it's plumb up I also had taken pic
                                of bathroom cabinet door had a mark on
                                it and one in kitchen as well
                                measurements taken TIME FOR REPAIR WILL
                                DEPEND ON GD RECOMMENDATION FOR FIX.
CORRECTION: Will need an approval to lower
                                underbelly and look at tank or bring
                                into shop.
WARR   COMPLAINT: KITCHEN CABINET DOOR HAS IMPERFECTION   W   1020   GRAND
                                MARKS ON BOTH THE INSIDE AND OUTSIDE OF
                                DOOR.
CAUSE:   MANUFACTURING IMPERFCTIONS IN WOOD IS
                                NOT SOMETHING THAT CAN BEW REPAIRED.
                                WILL NEED .20 TO REMOVE AND REPLACE.
CORRECTION: WILL NEED TO REPLACE WITH A NEW CABINET
                                DOOR APPROXIMATELT 18" X 24"
WARR   COMPLAINT: BATHROOM CABINET DOOR HAS AN           W   1020   GRAND
                                IMPERFECTION MARK ON THE OUTSIDE OF
                                CABINET DOOR
CAUSE:   IMPERFECTION MARK FROM MANUFACTURING IT
                                CANNOT BE REPAIRED. WILL NEED .2 TO
                                REMOVE AND REPLACE A CABINET DOOR.
CORRECTION: WILL NEED TO ORDER A REPLACEMENT DOOR
                                APPROXIMATELY 15" X 21".

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
SC SC SERVICE CHARGE JS E-90065 0.00 140.00 0.00
WARR RV28-31 SLIDE OUT ROOM DIAGNOS JS W-1020 1.00 115.00 115.00
WARR1 DIAG DIAGNOSTICS JS W-1020 1.00 115.00 115.00
WARR2 RV9-5 WATER SYSTEM DIAGNOSIS JS W-1020 0.50 115.00 57.50

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
SC SC SERVICE CALL E-90065 1.00 3.75 3.75
SC SSE SHOP SUPPLIES - EXTERNAL E-90065 1.00 0.00 0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
E 90065 0.00 0.00 0.00 3.75 0.21 3.96
W 1020 0.00 287.50 0.00 0.00 0.00 287.50

```

Continued on page 3

Work Order : 10559

\*\*\*\*\*

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	0.00	287.50	0.00	3.75	0.21	291.46

&k2S  
&k0S