



Warranty Claim Form

Date: 8/28/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3128R3350305
Reflection 270BN
Retail Purchase Date: null
Work Started: 7/3/2024
Work Completed: 7/3/2024

Claim Status: Paid
Dealer Work Order #: 10561B
Unit Offline Date: 5/13/2024

Claim #: 828029
Labor: \$57.50
Parts: \$0.00
Shipping: \$0.00
Total: \$57.50

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 620004 Floor Covering - Repair Linoleum (per *Fault Code:* Improper Installation/Build sq. yd.)

Problem: Linoleum has a small circle cut in it.

Hours: .5

Cause: Small circular hole from mfg in lino.

Amount: 57.50

Remedy: Cut the lino a bit then used glue to glue down, rolled out then used matching putty and pen to blend the area in with the rest of the floor.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: