

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10566

Date In: 29 MAY 24 Author: TPASSER
Promised Date: 25 DEC 24 Stock No: 11108
: Year: 2024
Customer Name: 107209 - LOENDORF, JIL Manufacturer: FOREST RIVER
Address: 106 WATERMAN AVE Brand: PUMA DESTINATION
: TOMAH, WI Model: 402LFT
Postal/Zip: 54660 Miles/Hrs: 0
Phone#(res): Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: 608-343-7611 License#:
Email: Tag#:
Purchased Date: 03 MAY 24 :
Delivery Date: 14 MAY 24 :
InService Date: :
Serial#: 4X4TPUS25RP101869 :

Job #	Description	JOB INFORMATION	Type	Bill To
SC	COMPLAINT: SERVICE CALL TO SHW SITE 105 UNDER LP COVER	**KEY	E	107209 LOEND
	CAUSE: CUSTOMER REQUEST			
	CORRECTION: COMPLETE			
WARR	COMPLAINT: UNIT DELIVERED 5/14 - CMR REPORTS WHEN USING AWNING - IT WENT OUT FINE BUT WOULD NOT COME BACK IN AT ALL.		W	1021 FORES
	CAUSE: the awning will extend out but will not retract without help checked voltage at switch 13.46 checked voltage at motor is 13 .46 I diagnose bad awning motor just in notes 4 prong awning switch			
	CORRECTION: INSTALLED NEW AWNING MOTOR- NOW OPERATES AS IT SHOULD			
WARR	COMPLAINT: CUSTOMER REPORTS DURING RAIN STORMS 5/26 - NOTICED TRICKLE OF WATER COMING OUT OF THE OUTLET NEXT TO THE COUCH-SMALL PUDDLE WITH WATER MARK TRAILING FROM OUTLET DOWN WALL.		W	1021 FORES
	CAUSE: inside towards front of camper there's outlets on both sides of couch I couldn't really duplicate want customer wanted but on exterior towards front of slide top seal had some opening in corners WILL NEED .5 FOR REPAIRS			
	CORRECTION: silicone sealant was used on corners of front top wiper seals			
WARR	COMPLAINT: CUSTOMER REPORTS FINDING 4 TRIM/BATTEN		W	1021 FORES

Continued on page 2

Work Order : 10566

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                STRIPS THAT ARE BUCKLING AWAY FROM WALL
                IN THE LIVINGROOM / KITCHEN AREA
CAUSE:   pics taken I only found two WILL NEED .2
                FOR REPAIRS
CORRECTION: secured batten strips with nailer and
                putty the nail holes
WARR    COMPLAINT: CUSTOMER REPORTS THAT THE BEDROOM DOOR   W    1021   FORES
                WILL NOT CLOSE WITHOUT LIFTING THE DOOR.
CAUSE:   what I found was the handle for the rear
                bedroom door was up to high and making
                the door lever not connecting with
                striker plate WILL NEED .3 FOR REPAIRS
CORRECTION: loosen the door handle and moved the
                handle downwards and tighten handle in
                correct position and tested after
                repairs the door now latches
    
```

```

*****
Job # Part No   Description                PARTS   Bill to   Qty   Price   Total
*****
WARR  848150042675 POWER MOTOR FOR V0002114 W-1021     1   276.85   276.85
WARR1 677917000333 10.3oz TUBE LAP SEALANT W-1021     2    9.14    18.28
    
```

```

*****
Job#  Lab Code  Description                LABOUR   Mech Bill to   Hrs   Rate   Total
*****
    SC SC      SERVICE CHARGE                JS   E-107209     0.50  140.00   70.00
WARR  DAWNING   AWNING DIAGNOIS                JS   W-1021     0.00  115.00    0.00
WARR1 W550      DIAGNOSIS AND TROUBLES JS   W-1021     0.20  115.00   23.00
WARR2 R500      TROUBLESHOOT AND DIAGN JS   W-1021     0.20  115.00   23.00
WARR3 PDADJUST PASSAGE DOOR ADJUST JS   W-1021     0.20  115.00   23.00
WARR  WARR     MANUFACTURER WARRANTY JS   W-1021     0.00  115.00    0.00
WARR  WARR     MANUFACTURER WARRANTY JS   W-1021     0.50  115.00   57.50
    
```

```

*****
Job #  Excode   Description                EXTRAS   bill to   Qty   Price   Total
*****
    SC SC      SERVICE CALL                E-107209  15.00   3.75   56.25
    SC SSE     SHOP SUPPLIES - EXTERNAL E-107209   1.00   5.25    5.25
    
```

```

*****
                                BILLINGS SUMMARY
Type Bill Id   Parts   Labour   Sublet   Extras   Tax   Total
*****
E   107209     0.00    70.00    0.00    61.50   7.26  138.76
W   1021     295.13  126.50    0.00    0.00   0.00  421.63

Totals     295.13  196.50    0.00    61.50   7.26  560.39
    
```

Continued on page 3

Work Order : 10566

&k2S
&k0S