

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497  
 GREENEWAY INC  
 DBA GREENEWAY RV SALES & SERVICE  
 8220 STATE HWY 13 SOUTH  
 WISCONSIN RAPIDS, WI 54494  
 USA

CLAIM STATUS Paid  
 CLAIM 2287908  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TFLN22N1901728  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010C  
 ITEM # FLT832BWS  
 DEALER RO # 10569  
 CLAIM START DATE 05/05/2025  
 CLAIM END DATE 07/08/2025

Labor rate: \$140.00

**OWNER INFORMATION**

HENRY PALMA  
 167707 WISCONSIN 153  
 Stratford, WI 54484  
 USA

Retail Date of Purchase 08/30/2024      WARRANTY EXPIRATION DATE 08/30/2025

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 RC-042-15-00-004215      22V556, 2022-368 - LCI AWNINGS 22E-055 - INSPECTION, REPAIR OR REPLACEMENT ONLY - Recall/Awning/Repair or Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-05-05 16:44:49 :: Complaint: Recall #22V556-LCI Cause: Recall Correction: Checked both awnings and did not find any separation issue Additional Note : greeneway@dealer-advisors.com, 2025-05-05 16:49:20 :: Previous PA 2088020 expired.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$140.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$42.00

**Notes**

Hello, as requested on the expired Claim 2088020 we need to see a photo of the separation at the weld as the photos do not show any issue or reason to replace. the photos would indicate this is an inspect only  
 Yes, and I only entered what was approved prior. This was approved for 1 hour on the previous PA.  
 hello, the previous claim was denied and noted due to not having the photo required.  
 authorized for inspect only.

**Labor**

Line# 2      **Operation Code**      **Operational Description**  
 SB-400-15-00-004200      10-1526 – TETON WIFI RANGER ROOF MOUNT INSPECTION AND REPLACEMENT - Technical Service Bulletin/Electronic Components/Repair or Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : greeneway@dealer-advisors.com, 2025-05-05 16:46:57 :: Complaint: Unit recall # 10-1526-WIFI Cause: Recall range extender Correction: The head is cracked and will need replacement. Additional Note : greeneway@dealer-advisors.com, 2025-05-05 16:49:14 :: Previous PA 2088020 expired.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.50	<b>Sub Labor Amt</b>	\$70.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$70.00

**Notes**

**Part**

Line# 1      **Item #**      **Description**  
 F100291853      ANTENNA - OOS: STEREO, TV, AND WIFI COMBINATION ANTENNA W/ CABLE ENTRY PLATE, TETON - V# WR-0101 | PCN 10G-0484/0619, PCN 10D-1579F100291853 -/1801, PCN 10C-2224/2409/2539, PCN 10T-0929/1027/1205, INTERNAL USE ONLY – CHECK FOR TSB

<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>
----------------	-----------------	-----------------

Sub Qty 1.00  
Appr Qty 1.00

Sub Dlr Price \$304.06  
Appr Dlr Price \$304.06

Sub Freight \$21.02  
Appr Freight \$21.02

Notes

---

**Submitted**

Labor Amt \$210.00  
Parts & Freight \$325.08  
Total \$535.08

**Approved**

Labor Amt \$112.00  
Parts & Freight \$325.08  
Total \$437.08

---

**DEALER** \_\_\_\_\_ **DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** \_\_\_\_\_ **DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.