

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10622

Date In:	10 JUN 24	Author:	KOTT
Promised Date:	15 JUN 24	Stock No:	11070
:	:	Year:	2024
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE AIM
:	MIDDLEBURY, IN	Model:	15RB
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	db 6/12
Purchased Date:	04 APR 24	:	:
Delivery Date:	19 APR 24	:	:
InService Date:	:	:	:
Serial#:	573TE2018R7702048	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - CUSTOMER STATES THAT W    1020    GRAND
          THE CLOSET DOOR TO THE LEFT OF THE
          MURPHY BED- IF YOU ARE STANDING IN FRONT
          OF IT AND LOOKING AT IT- SCRAPES THE
          CEILING
          CAUSE:      Cabinet door adjustment
          CORRECTION: Adjusted European hinges on cabinet door
          left side of bed to clear ceiling.
          Tested good.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CUSTOMER STATES THAT W    1020    GRAND
          THERE IS A LEAK BY THE BLACK WATER-
          CUSTOMER STATES THAT THERE IS A HOSE
          THAT COMES DOWN FROM THAT AREA AND IT IS
          DRIPPING WATER-
          CAUSE:      Check black tank for leak.
          CORRECTION: Filled black tank up to 2/3 full and
          wait for it to leak. Also filled Grey
          tank. Couldn't reproduce leak at this
          time.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - CUSTOMER STATES THAT W    1020    GRAND
          THE KITCHEN SINK IS LEAKING- UNDERNEATH
          INTO THE CABINET- CMR STATES THAT THE
          LEAK IS COMING FROM THE FAUCET, AND
          BELIEVES THERE IS A GASKET INSIDE THAT
          IS DEFECTIVE.
          CAUSE:      Check for leak under kitchen sink.
          CORRECTION: Pressurized system with water. I moved
          the water lines around to see if the
```

Continued on page 2

Work Order : 10622

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
lines would leak. No leak as of yet.
Turned faucet on to see if the drain had
a leak and found none. No leaks at this
time. After further review, removed
faucet and gasket was out of place. put
gasket on correctly and had no further
issue. done.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - BEDROOM LEFT NIGHT  W    1020    GRAND
          STAND - BOTTOM DRAWER NOT OPERATING
          CORRECT - CMR WILL MARK W/ POST-IT.
          CAUSE:      Drawer left side of Murphy bed is out of
          track.
          CORRECTION: Reinstall drawer glide in track. Tested
                      good.
1        FRONT JACK RUBBER PLUG WAS LOST BY CMR, PLEASE      E    17278  HILDE
          REPLACE

```

```

*****
Job # Part No Description      PARTS      Bill to  Qty    Price    Total
*****
1      82206570 TONGUE JACK, RUBBER PLUG ONL E-17278      1      10.85    10.85

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.10    115.00    11.50
ARR02 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.10    115.00    11.50
ARR03 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.10    115.00    11.50
ARR04 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.10    115.00    11.50
ARR02 Z992      MISC LABOUR CODE (WARR TD  W-1020    0.41    115.00    47.15

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    17278        10.85        0.00        0.00        0.00        0.61      11.46
W    1020         0.00        93.15        0.00        0.00        0.00      93.15

Totals          10.85        93.15        0.00        0.00        0.61      104.61

```

&k2S
&k0S