

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10622

Date In:	10 JUN 24	Author:	KOTT
Promised Date:	15 JUN 24	Stock No:	11070
:	:	Year:	2024
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	IMAGINE AIM
:	MIDDLEBURY, IN	Model:	15RB
Postal/Zip:	46540	Miles/Hrs:	:
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	04 APR 24	:	:
Delivery Date:	19 APR 24	:	:
InService Date:	:	:	:
Serial#:	573TE2018R7702048	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - CUSTOMER STATES THAT W    1020    GRAND
          THE CLOSET DOOR TO THE LEFT OF THE
          MURPHY BED- IF YOU ARE STANDING IN FRONT
          OF IT AND LOOKING AT IT- SCRAPES THE
          CEILING
          CAUSE:      Cabinet door adjustment
          CORRECTION:  Adjusted European hinges on cabinet door
          left side of bed to clear ceiling.
          Tested good.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CUSTOMER STATES THAT W    1020    GRAND
          THERE IS A LEAK BY THE BLACK WATER-
          CUSTOMER STATES THAT THERE IS A HOSE
          THAT COMES DOWN FROM THAT AREA AND IT IS
          DRIPPING WATER-
          CAUSE:      Check black tank for leak.
          CORRECTION:  Filled black tank up to 2/3 full and
          wait for it to leak. Also filled Grey
          tank. Couldn't reproduce leak at this
          time.
WARR    COMPLAINT:  WARRANTY REPAIR 3 - CUSTOMER STATES THAT W    1020    GRAND
          THE KITCHEN SINK IS LEAKING- UNDERNEATH
          INTO THE CABINET-
          CAUSE:      Check for leak under kitchen sink.
          CORRECTION:  Pressurized system with water. I moved
          the water lines around to see if the
          lines would leak. No leak as of yet.
          Turned faucet on to see if the drain had
          a leak and found none. No leaks at this
```

Continued on page 2

Work Order : 10622

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
time.
WARR    COMPLAINT:  WARRANTY REPAIR 4 - BEDROOM LEFT NIGHT  W    1020    GRAND
          STAND - BOTTOM DRAWER NOT OPERATING
          CORRECT - CMR WILL MARK W/ POST-IT.
CAUSE:   Drawer left side of Murphy bed is out of
          track.
CORRECTION: Reinstall drawer glide in track. Tested
          good.
1        FRONT JACK RUBBER PLUG WAS LOST BY CMR, PLEASE      E    17278    HILDE
          REPLACE

```

```

*****
Job # Part No Description      PARTS      Bill to Qty Price Total
*****
1      82206570 TONGUE JACK, RUBBER PLUG ONL E-17278      1    10.85    10.85

```

```

*****
Job# Lab Code Description    LABOUR    Mech Bill to Hrs Rate Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020 0.10 115.00 11.50
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1020 0.10 115.00 11.50
ARR03 Z992 MISC LABOUR CODE (WARR TD W-1020 0.10 115.00 11.50
ARR04 Z992 MISC LABOUR CODE (WARR TD W-1020 0.10 115.00 11.50
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1020 0.41 115.00 47.15

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    17278        10.85        0.00        0.00        0.00        0.61        11.46
W    1020         0.00        93.15        0.00        0.00        0.00        93.15
Totals          10.85        93.15        0.00        0.00        0.61        104.61

```

&k2S
&k0S