

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10644B

Date In: 21 JUN 24 Author: MGRAY  
Promised Date: 20 JUN 24 Stock No: 11067  
: Year: 2024  
Customer Name: 16177 - WALLOCH, DONAL Manufacturer: CROSSROADS  
Address: 1510 SHERWOOD CT Brand: HAMPTON  
: WISCONSIN RAPIDS, WI Model: 370FDL  
Postal/Zip: 54494 Miles/Hrs: 0  
Phone#(res): (715) 459-2449 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: DCWALLOCH@GMAIL.COM Tag#: DEL @ST  
Purchased Date: 11 JUN 24 :  
Delivery Date: 20 JUN 24 :  
InService Date: :  
Serial#: 4YDTHPT28R9330258 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - PANTRY TRIM CRACKED, TOP PIECE HAS CRACK NEEDS REPLACEMENT. CAUSE: LOOKS LIKE IT MAY HAVE STARTED AS A SMALL CRACK AND HAS EXPANDED POSSIBLY WITH WEATHER. WILL NEED .10 TO REMOVE AND REPLACE THE TRIM PEICE. CORRECTION: WILL NEED TO ORDER AND REMOVE OLD TRIM AND REPLACE WITH NEW PEICE.		W	1021 FORES
WARR	WARRANTY REPAIR 2 - UPPER LOFT CLOSET ABOVE BEDROOM. BOTTOM PART OF CLOSET IS PUSHED UP AND NOT SEATED CORRECTLY.		W	1025 KEYST
WARR	COMPLAINT: TV HAS LINES RUNNING THROUGH THE PICTURE, IT ALSO FLASHES IN AND OUT OF PICTURE. PICTURES AND VIDEO TAKEN. CAUSE: DEFECT IN TV. UNPLUGGED TV TO RESET IT AND IT WAS FIND FOR APPROXIMATELY ONE MINUTE THEN SCRAMBLED AGAIN. WILL NEED .3 TO INSTALL AND HOOK UP A NEW TV. CORRECTION: WILL NEED TO ORDER A REPLACEMENT TV THROUGH WARRANTY.		W	1025 KEYST
WARR	COMPLAINT: DENT IN LEFT SIDE REFRIGERATOR DOOR. ONLY NOTICABLE WHEN YOU STAND AT A CERTAIN ANGLE CUSTOMER NOTICED DURING SHOW THROUGH AND WOULD LIKE REPLACED. CAUSE: LOOKS LIKE IT MAY HAVE BEEN HIT BY THE PANTRY DOOR HANDLE ADJACENT TO REFRIGERATOR, SUGGEST TO MFG AND CUSTOMER TO PUT A DOOR BUMBER ON PANTRY		W	1025 KEYST

Continued on page 2

Work Order : 10644B

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
                                DOOR OR THIS MAY OCCUR AGAIN. WILL NEED
                                .3 TO REMOVE AND REPLACE REFRIGERATOR
                                DOOR.
CORRECTION: WILL NEED A REPLACEMENT REFRIGERATOR
                                DOOR PICS OF MODEL UPLOADED.
WARR    COMPLAINT:  BROKEN PLASTIC SIDE ON AIR VENT IN THE     W    1025   KEYST
                                BUNK LOFT. PIECE IS COMPLETELY MISSING
                                FROM THE SIDE.PICTURES TAKEN
CAUSE:    MISSING WHEN INSTALL, THERE ARE NO
                                PIECES LAYING ANYWHERE THAT WOULD HAVE
                                BROKEN OFF. WILL NEED .2 TO REMOVE AND
                                REPLACE PLASTIC SHROUD OR .1 TO REPLACE
                                JUST MISSING PIECE IF IT IS AVAILABLE.
CORRECTION: REPLACE MISSING PLASTIC PIECE.
WARR    WARRANTY REPAIR 6 - FAN IN BATHROOM IS VERY LOUD.     W    1021   FORES
                                SOUNDS OFF KILTER. NEED NEW FAN.

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR    W-1021    0.00  115.00  0.00
ARR02 Z992    MISC LABOUR CODE (WARR    W-1025    0.00  105.00  0.00
ARR03 Z992    MISC LABOUR CODE (WARR    W-1025    0.00  105.00  0.00
ARR04 Z992    MISC LABOUR CODE (WARR    W-1025    0.00  105.00  0.00
ARR05 Z992    MISC LABOUR CODE (WARR    W-1025    0.00  105.00  0.00
ARR06 Z992    MISC LABOUR CODE (WARR    W-1021    0.00  115.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
Totals        0.00   0.00   0.00   0.00   0.00   0.00

```

&k2S  
&k0S