

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10665B

Date In: 27 JUN 24 Author: KOTT  
Promised Date: 04 JUL 24 Stock No: 11157  
: Year: 2024  
Customer Name: 17318 - HURLEY, JOHN Manufacturer: CROSSROADS  
Address: 1059 ROWLAND ROAD Brand: HAMPTON  
: OSHKOSH, WI Model: 375DBL  
Postal/Zip: 54904 Miles/Hrs: 0  
Phone#(res): 9203798494 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: NOW SOLD TO HURLEY  
Purchased Date: 04 MAY 24 :  
Delivery Date: 27 JUN 24 :  
InService Date: :  
Serial#: 4YDTHPT29R9330480 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
WARR COMPLAINT: WARRANTY REPAIR 1 - screen above sofa W 1047 CROSS  
frame is dented  
CAUSE: Noting  
CORRECTION: Noting  
WARR COMPLAINT: WARRANTY REPAIR 2 - side of slides W 1047 CROSS  
inside wood trim is rough  
CAUSE: Mfg left unfinished. TOOK .50 TO SAND  
DOWN ALL EDGES SMOOTHLY.  
CORRECTION: Used sand paper to smooth rough edge.  
WARR COMPLAINT: WARRANTY REPAIR 3 - drawer in pantry W 1047 CROSS  
does not opening correctly  
CAUSE: The glide on left side is brokePlease  
order 1 1/4" when closed drawer glide  
the right side is needed. I will  
reinstall the faulty one it still works  
but is finicky I will need .40 for diag  
and repairs.  
CORRECTION: ..... REQUEST .50 HOURS OF LABOR  
PLUS PARTS  
WARR COMPLAINT: WARRANTY REPAIR 4 - next to tv the panel W 1047 CROSS  
has deep scratch  
CAUSE: Noting  
CORRECTION: Noting if cust sees it not a bad scratch  
WARR COMPLAINT: WARRANTY REPAIR 5 - loose trim W 1047 CROSS  
throughout unit several peices of batten  
were coming loose.  
CAUSE: Loose batten not secured correctly. will

Continued on page 2

Work Order : 10665B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        need .30 to resecure all loose batten in
        unit.
CORRECTION: Used nail gun to secure trim throughout
unit
WARR    COMPLAINT:  WARRANTY REPAIR 6 - all 3 slide exterior W    1047    CROSS
        bottoms have exposed screw holes
CAUSE:   Mfg never filled holes on underside of
        slide floors I will need .30 for all
        repairs.
CORRECTION: Used black silicone to fill holes on all
        3 slides
WARR    COMPLAINT:  WARRANTY REPAIR 7 - marker lights have    W    1047    CROSS
        no sealant around them
CAUSE:   No sealant around lower running light I
        will need .10 for repairs.
CORRECTION: Used clear silicone to seal around
        lights
WARR    COMPLAINT:  WARRANTY REPAIR 8 - drawer next to stove W    1047    CROSS
        the backer wood for drawer face is
        cracked
CAUSE:   Cracked from mfg. Please order new
        drawer, face is 12"w x 6" t. Inner
        dimension 22"deep x10"wide
CORRECTION: ..... REQUEST .60 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 9 -no sealant on counter W    1047    CROSS
        tops next to sofa
CAUSE:   Missing sealant, missed by manufacturer.
        will need .60 to clean and seal
        countertops.
CORRECTION: Sealed countertop edges
WARR    COMPLAINT:  WARRANTY REPAIR 10 - ceiling trip ends    W    1047    CROSS
        are separating and bubbled
CAUSE:   Mfg installed faulty battertn. will need
        .20 for repairs.
CORRECTION: Cut a slit then used glue to secure the
        paper to wood
WARR    COMPLAINT:  WARRANTY REPAIR 11 - the valance above    W    1047    CROSS
        patio the side panels are too long and
        bath door hits it
CAUSE:   Mfg improper install
CORRECTION: Removed and cut wood off sides of
        valance and top reattached now but it is
        still hitting. what does MFG want us to
        do?

```

```

*****
Job# Lab Code Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1047 0.00 105.00 0.00

```

Continued on page 3

Work Order : 10665B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.10   105.00   10.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1047    1.00   105.00  105.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.50   105.00   52.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.50   105.00   52.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.20   105.00   21.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.20   105.00   21.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.10   105.00   10.50
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.00   105.00    0.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.50   105.00   52.50
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.50   105.00   52.50
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.20   105.00   21.00
ARR11 Z992      MISC LABOUR CODE (WARR HOD W-1047    0.50   105.00   52.50
*****
```

```
*****
Job #  Excode   Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1047  1.00   0.00   0.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
W      1047      0.00   451.50   0.00   0.00   0.00   451.50
*****
Totals      0.00   451.50   0.00   0.00   0.00   451.50
*****
```

&k2S  
&k0S