

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10673

Date In: 19 JUN 24 Author: MGRAY
Promised Date: 25 DEC 24 Stock No:
: Year: 2023
Customer Name: 114808 - KWASNY, PAUL Manufacturer: GRAND DESIGN
Address: 6801 RUNNING HORSE ROA Brand: REFLECTION TT
: RACINE, WI Model: 315RSTS
Postal/Zip: 53402 Miles/Hrs:
Phone#(res): 262-994-8014 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: P.CHERYLL@SBCGLOBAL.NE Tag#: CMR PICKING UP 10/23
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: :

Job # Description JOB INFORMATION Type Bill To

WS COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF E 114808 KWASN
CONTAINED - TOWABLE
CAUSE: Winterize coach
CORRECTION: Washer & 5gal of antifreeze. Ran 20min
of quick cycle on washer.
Winterized.
RI COMPLAINT: PREFORM ROOF INSPECTION AND ADVISE IF I SEP POLIC
REPAIR IS NEEDED.
CAUSE: Request roof inspection
CORRECTION: Inspected roof membrane and sealants for
possible issues. All sealants and
membranes are clean and of quality
condition. Sealants are adequate and in
appropriate condition to withhold
moisture intuition. No further
action necessary.
WARR COMPLAINT: WARRANTY REPAIR 1 - VENT IN THE BATHROOM W 1020 GRAND
IS NOT CLOSING TIGHT. SEEMS LIKE IT IS
STRIPPED
CAUSE: Clip too tight
CORRECTION: Clip that holds cent lid centered was
too tight, not allowing lid to close
completely. Bent out wings on clip
slightly, closing fine now.
WARR COMPLAINT: WARRANTY REPAIR 2 - BLACK TANK SMELL, W 1020 GRAND
COMING FROM BY FURNACE, NOT FROM THE
BATHROOM. UNSURE IF WE WILL BE ABLE TO
SMELL IT, EVEN WHEN USING THE TABLETS IN

Continued on page 2

Work Order : 10673

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                                THE TANK FOR THE SMELL 2-3 AT A TIME AND
                                STILL HAVING SMELLS
CAUSE:      Request investigate smell issue by
                                furnace.      Two separate tank vents
                                merge to one where issue is presiding.
CORRECTION: Black tanks smell even when using chems,
                                they don't completely mask smells,
                                they're more for the process of braking
                                down solids.      Did not find anything
                                unusual with plumbing, everything is
                                tied together appropriately and seals to
                                tank are intact. Used the inspection
                                camera to gain access.      Did see a
                                couple mouse droppings around furnace
                                area, could be the potential smell.
MF      COMPLAINT:  MOUSE FREE UNDERCARRIAGE LUBRICANT           E      114808 KWASN
                                APPLIED TO CAMPER.  (Per Linear Foot)
                                The product is designed to prevent entry
                                of mice into Recreational Vehicles by
                                preventing entry through the small holes
                                that exist to accomodate the passage of
                                wires and hoses within the undercarriage
                                or under body of a trailer or motor
                                home.
CAUSE:      Request mouse free
CORRECTION: Mouse free applied to underbelly and
                                frame
1      COMPLAINT:  CHECK TIRE PRESSURE                           E      114808 KWASN
CAUSE:      Request check tire pressure
CORRECTION: Front DS 72.2, Rear DS 73.5.  Rear ODS
                                73.9, Front ODS 72.9

```

```

*****
Job # Part No   Description           PARTS   Bill to   Qty   Price   Total
*****
WS     009114950003  -50 F GLYCERIN FREE BASE E-11480   3     10.38   31.14
MF     51700005      MOUSE FREE (5GAL BULK) P E-11480  31     14.75  457.25

```

```

*****
Job# Lab Code Description           LABOUR   Mech Bill to   Hrs   Rate   Total
*****
WS W495 WINTERIZE RV (WATER SY RW E-114808  0.63  140.00  88.20
RI Z991 PREFORM ROOF INSPECTIO RW I-SEP    0.30   70.00  21.00
ARR01 Z992 MISC LABOUR CODE (WARR RW W-1020   0.50  115.00  57.50
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1020   0.00  115.00   0.00
MF Z990 APPLY MOUSEFREE UNDERC RW E-114808  0.50   70.00  35.00
1 Z990 MISC LABOUR CODE (EXTE RW E-114808  0.10  140.00  14.00
ARR02 Z992 MISC LABOUR CODE (WARR RW W-1020   0.12  115.00  13.80
WS W495 WINTERIZE RV (WATER SY RW E-114808  0.07  140.00   9.80

```

Continued on page 3

Work Order : 10673

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR RW  W-1020    0.03   115.00    3.45
ARR02 Z992      MISC LABOUR CODE (WARR RW  W-1020    0.35   115.00   40.25
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
  WS   J-ADJ      QUOTE ADJUSTMENT      E-114808  1.00   -24.14   -24.14
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E   114808      488.39   147.00    0.00    -24.14   33.64   644.89
I   SEP         0.00    21.00    0.00     0.00    0.00    21.00
W   1020         0.00   115.00    0.00     0.00    0.00   115.00

Totals      488.39   283.00    0.00    -24.14   33.64   780.89
*****
```

&k2S
&k0S