

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10678

Date In:	20 JUN 24	Author:	MZYWICKI
Promised Date:	24 APR 25	Stock No:	
:		Year:	2023
Customer Name:	17383 - GAMLIN, ERIK	Manufacturer:	FOREST RIVER
Address:	1348 GLACIER DR	Brand:	WILDWOOD
:	BYRON, IL	Model:	42FK
Postal/Zip:	61010	Miles/Hrs:	
Phone#(res):	8159044825	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	ERIKGAMLIN@YAHOO.COM	Tag#:	4/24
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	4X4TWD829PM062275	:	

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
1       MOBILE SERVICE CALL TO OASIS CAMPGROUND SITE #79        E    17383  GAMLI
      ***THERE IS A KEY TO THE UNIT IN A MAGNETIC KEY BOX
      BY THE WATER HEATER*** *****SERVICE CALL IS TO BE
      BILLED TO GENERAL RV- ATTENTION JASON- GENERAL RV
      (847)669-5570
2       COMPLAINT:  CUSTOMER STATES THAT THE KITCHEN TABLE      W    1021  FORES
      IS STARTING TO BUBBLE UP-
      CAUSE:         pics and measurements taken of kitchen
      table the paint peeled and bubbles will
      need a new table
      CORRECTION:    remove the scuffed table top from floor
      base install the new table top to old
      floor base the table is now ok
3       COMPLAINT:  CUSTOMER STATES THAT THE EMERGENCY EXIT      W    1021  FORES
      HANDLE IS BROKEN OFF- IT IS THE WINDOW
      THAT IS ABOVE THE KITCHEN TABLE-
      CAUSE:         pics taken the handle is broken and is
      replaceable
      CORRECTION:    remove and install the new emergency
      latch on window in kitchen
4       COMPLAINT:  CUSTOMER REQUESTS HAVING THE KITCHEN        W    1021  FORES
      BLIND DOES NOT GO ALL THE WAY DOWN- IT
      IS THE BLIND THAT IS RIGHT NEXT TO THE
      FRIDGE-
      CAUSE:         pics taken and the shade has holes in it
      and doesn't pull all the way down
      CORRECTION:    REPALCED
5       COMPLAINT:  CUSTOMER STATES THAT THE BATTERY COVER      W    1021  FORES
```

Continued on page 2

Work Order : 10678

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
        IS MISSING-
CAUSE:   pics and measurements taken they have
        the wrong size battery box cover
CORRECTION: remove and install new battery box with
        cover
6        COMPLAINT: CUSTOMER STATES THAT THE PANTRY DOOR        W        1021    FORES
        CAUGHT ON THE SLIDE AND BROKE THE PANTRY
        DOOR (THE HANDLE BENT INTO THE WOOD)
CAUSE:   pics and measurements taken of door and
        handle will need a new door handle
        assembly I did take pics of door just in
        case the door is a little scuffed up
        around door handle so that's your call
CORRECTION: remove the damage door from pantry
        measurements taken install the existing
        hinges onto new door and re attached to
        pantry framework the door is now ok
WS        WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED -    E        17383    GAMLI
        TOWABLE

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      82205369     TABLE, DINETTE TOP, 26" W-1021      1      157.05     157.05
6      82207808     DOOR, PASSAGE, 20 X 74, W-1021      1      184.02     184.02
6      82203987     PASSAGE LATCH, NON LATCH W-1021      1        8.15        8.15
5      014717553728 GROUP 27 30 31 BATTERY B W-1021      1       12.75       12.75
3      822046211     LATCH ,WINDOW - RED - EX W-1021      1        2.87        2.87
WS     071247312003 WINTERSAFE -50 ANTIFREEZ E-17383      3       10.69       32.07
4      822068801     SHADE, ROLLER, 31" X 44" W-1021      1       40.00       40.00

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to      Hrs      Rate      Total
*****
2  WARR        MANUFACTURER WARRANTY JS    W-1021      0.30     115.00     34.50
3  WARR        MANUFACTURER WARRANTY JS    W-1021      0.35     115.00     40.25
4  WARR        MANUFACTURER WARRANTY JS    W-1021      0.30     115.00     34.50
5  WARR        MANUFACTURER WARRANTY JS    W-1021      0.20     115.00     23.00
6  WARR        MANUFACTURER WARRANTY JS    W-1021      1.00     115.00    115.00
2  WARR        MANUFACTURER WARRANTY JS    W-1021      0.50     115.00     57.50
3  WARR        MANUFACTURER WARRANTY JS    W-1021      0.50     115.00     57.50
4  WARR        MANUFACTURER WARRANTY JS    W-1021      0.50     115.00     57.50
5  WARR        MANUFACTURER WARRANTY JS    W-1021      0.50     115.00     57.50
6  WARR        MANUFACTURER WARRANTY JS    W-1021      0.50     115.00     57.50
WS W495        WINTERIZE RV (WATER SY JS    E-17383      0.70     140.00     98.00

```

Continued on page 3

Work Order : 10678

```

*****
Job #  Excode   Description   EXTRAS      bill to      Qty      Price      Total
*****
   1  SSE       SHOP SUPPLIES - EXTERNAL  E-17383    1.00       7.35       7.35
   1  SC        SERVICE CALL              E-17383   24.00       3.75      90.00
   6  FRT       FREIGHT                   W-1021     1.00      21.00      21.00
   2  FRT       FREIGHT                   W-1021     1.00      40.46      40.46
   4  FRT       FREIGHT FOR SHADE AND WIND W-1021     1.00      21.05      21.05
   6  FRT       FREIGHT                   W-1021     1.00     199.91     199.91
   1  SC        SERVICE CALL              E-17383   24.00       3.75      90.00
WS   J-ADJ     QUOTE ADJUSTMENT          E-17383     1.00     -25.07     -25.07
   4  FRT       FREIGHT                   W-1021     1.00      21.02      21.02
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E   17383          32.07       98.00        0.00      162.28      16.09      308.44
W   1021          404.84      534.75        0.00      303.44        0.00     1,243.03

      Totals          436.91      632.75        0.00      465.72      16.09     1,551.47

```

&k2S
&k0S