

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10690B

Date In: 03 JUL 24 Author: KOTT
Promised Date: 25 DEC 24 Stock No: 11130
: Year: 2024
Customer Name: 17386 - RYAN, LAURA Manufacturer: GRAND DESIGN
Address: E8601 HOGSBACK ROAD Brand: TRANSCEND XPLOR
: Model: 221RB
Postal/Zip: 53913 Miles/Hrs: 0
Phone#(res): 8153417557 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: mlk2ryan88@gmail.com Tag#: PU@ST
Purchased Date: 22 JUN 24 :
Delivery Date: 25 DEC 24 :
InService Date: :
Serial#: 573TT2721R8831375 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - LP quick connect is broken	WARRANTY REPAIR 1 - LP quick connect is broken	W	1020 GRAND
	CAUSE: Missing lp quick connect handle NEED .70 FOR REPAIR			
	CORRECTION: Removed bad lp connection and Installed new one with lp tape then performed manometer test and it passed			
WARR	COMPLAINT: WARRANTY REPAIR 2 - Silicone around bathroom sink is put on very sloppily smeared all over the sink edge	WARRANTY REPAIR 2 - Silicone around bathroom sink is put on very sloppily smeared all over the sink edge	W	1020 GRAND
	CAUSE: Mfg done during manufacturing of unit. WILL NEED .50 TO CLEAN UP, REMOVE OLD SILICONE AND REAPPLY NEW SILICONE.			
	CORRECTION: Cleaned off bad silicone job and applied clear sealant around the sink			
WARR	COMPLAINT: WARRANTY REPAIR 3 - There is a loose trim in the bedroom door side corner	WARRANTY REPAIR 3 - There is a loose trim in the bedroom door side corner	W	1020 GRAND
	CAUSE: Loose trim,not properly secured from mfg. will need .20 to resecure properly.			
	CORRECTION: Used pin nailer to secure			
WARR	COMPLAINT: WARRANTY REPAIR 4 -Silicone is squishing out from beneath the wardrobe off door side wardrobe cabinet door	WARRANTY REPAIR 4 -Silicone is squishing out from beneath the wardrobe off door side wardrobe cabinet door	W	1020 GRAND
	CAUSE: Improper install of sealant for mirror. will need .20 to clean and reapply silicone.			
	CORRECTION: I carefully cut the dried clear silicone away			

Continued on page 2

Work Order : 10690B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - I am unable to find W   1020   GRAND
        the keys for this unit
        CAUSE:      Found NOTHING MISSING
        CORRECTION: Found NOTHING MISSING
WARR    COMPLAINT:  WARRANTY REPAIR 13 - tv screen has deep W   1020   GRAND
        scratches
        CAUSE:      Scratched tv screen Please order new tv
                   TCL North America model 32S350G Pic of
                   model and serial tag taken WILL NEED .50
                   to remove and replace a working TV
        CORRECTION: will need a replacement TV.

```

```

*****
Job # Part No  Description           PARTS           Bill to  Qty   Price   Total
*****
WARR0 822020061 QUICK DISCONNECT X 1/4 BRAS W-1020      1     14.30   14.30

```

```

*****
Job#  Lab Code  Description           LABOUR   Mech Bill to  Hrs   Rate   Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR02 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR03 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR04 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR05 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50
ARR13 Z992     MISC LABOUR CODE (WARR HOD W-1020      0.50  115.00  57.50

```

```

*****
Job #  Excode   Description           EXTRAS           bill to  Qty   Price   Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL W-1020      1.00   0.00   0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id           Parts   Labour   Sublet   Extras   Tax   Total
*****
W      1020             14.30   345.00   0.00    0.00    0.00   359.30
      Totals           14.30   345.00   0.00    0.00    0.00   359.30

```

&k2S
&k0S