

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10690B

Date In:	03 JUL 24	Author:	KOTT
Promised Date:	25 DEC 24	Stock No:	11130
:	:	Year:	2024
Customer Name:	17386 - RYAN, LAURA	Manufacturer:	GRAND DESIGN
Address:	E8601 HOGSBACK ROAD	Brand:	TRANSCEND XPLORE
:	BARABOO, WI	Model:	221RB
Postal/Zip:	53913	Miles/Hrs:	0
Phone#(res):	8153417557	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	mlk2ryan88@gmail.com	Tag#:	PU@ST
Purchased Date:	22 JUN 24	:	:
Delivery Date:	26 JUL 24	:	:
InService Date:	:	:	:
Serial#:	573TT2721R8831375	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - LP quick connect is W    1020    GRAND
        broken
        CAUSE:      Missing lp quick connect handle NEED .70
        FOR REPAIR
        CORRECTION: Removed bad lp connection and Installed
        new one with lp tape then performed
        manometer test and it passed
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Silicone around      W    1020    GRAND
        bathroom sink is put on very sloppily
        smeared all over the sink edge
        CAUSE:      Mfg done during manufacturing of unit.
        WILL NEED .50 TO CLEAN UP, REMOVE OLD
        SILICONE AND REAPPLY NEW SILICONE.
        CORRECTION: Cleaned off bad silicone job and applied
        clear sealant around the sink
WARR    COMPLAINT:  WARRANTY REPAIR 3 - There is a loose      W    1020    GRAND
        trim in the bedroom door side corner
        CAUSE:      Loose trim,not properly secured from
        mfg. will need .20 to resecure properly.
        CORRECTION: Used pin nailer to secure
WARR    COMPLAINT:  WARRANTY REPAIR 4 -Silicone is squishing W    1020    GRAND
        out from beneath the wardrobe off door
        side wardrobe cabinet door
        CAUSE:      Improper install of sealant for mirror.
        will need .20 to clean and reapply
        silicone.
        CORRECTION: I carefully cut the dried clear silicone
        away
```

Continued on page 2

Work Order : 10690B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 5 - I am unable to find W    1020    GRAND
          the keys for this unit
          CAUSE:      Found NOTHING MISSING
          CORRECTION: Found NOTHING MISSING
WARR    COMPLAINT:  WARRANTY REPAIR 13 - tv screen has deep W    1020    GRAND
          scratches
          CAUSE:      Scratched tv screen Please order new tv
          TCL North America model 32S350G Pic of
          model and serial tag taken WILL NEED .50
          to remove and replace a working TV.
          CORRECTION: will need a replacement TV.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822020061    QUICK DISCONNECT X 1/4 B W-1020      1      14.30      14.30
WARR0 677917000333 10.3oz TUBE LAP SEALANT W-1020      1      9.14      9.14
WARR0 677917000333 10.3oz TUBE LAP SEALANT W-1020      1      9.14      9.14
WARR1 8220740294    TV 32" TCL GOOGLE SMART W-1020      1     339.11     339.11

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.70     115.00     80.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.20     115.00     23.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.20     115.00     23.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.30     115.00     34.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.50     115.00     57.50
ARR13 Z992      MISC LABOUR CODE (WARR HOD W-1020      0.30     115.00     34.50

```

```

*****
Job # Excode Description EXTRAS bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1020      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      371.69      253.00      0.00      0.00      0.00      624.69

Totals      371.69      253.00      0.00      0.00      0.00      624.69

```

&k2S
&k0S