

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	1995324
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2FSJC5N3026657
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$115.00	SITE/WAREHOUSE	010 / 010G
OWNER INFORMATION		ITEM #	FLTE19FDS
GENE FOSNAUGH		DEALER RO #	10719
2001 Riverview Ave, Lot 93		CLAIM START DATE	07/23/2024
Stevens Point, WI 54481		CLAIM END DATE	07/28/2024
USA			
Retail Date of Purchase	03/21/2024	WARRANTY EXPIRATION DATE	03/21/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-69-02-00-000705	Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-07-23 16:22:43 :: Complaint: Locks on compartment door are not easy to open. One has a broken key in it. Will tape all doors with issues. Cause: Compartment door latch adjustment. Correction: Change a couple of strikers on compartment doors and adjusted the others for smoother operation.			
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
Serial#		Appr Hrs	0.50	Appr Labor Amt \$57.50
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-136-24-00-001497	Fresh Water Tank - Plumbing/Fresh Water Supply/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-07-23 16:25:15 :: Complaint: Filled fresh water tank and pulled over to site from fill station. There was water in the front compartment. Not water damage, first time this has happened. Cause: Test gravity fresh water fill for leaks. Customer says they had water in the front storage after filling tank. Correction: Filled fresh tank completely full until water came out of the gravity fill spout. Could not produce any leaks.			
Model#		Dlr Sub Hrs	0.50	Sub Labor Amt \$57.50
Serial#		Appr Hrs	0.50	Appr Labor Amt \$57.50
	Notes			
	Hi there, please provide pictures showing the issue found.			
	Photos were not taken after testing due to no leak being found- this is a NPF line, just asking for diagnosis time. Thank you!			
	Goodwill			

Labor

Line# 3	Operation Code	Operational Description		
	20-46-24-00-000726	Window Screen - Exterior/Windows/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2024-07-23 16:26:29 :: Complaint: Screen on window is not flush with window. May need adjustment. Cause: Window above the dinette table has a screen adjustment to be made. Correction: Adjusted the screen frame for better fit.			
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt \$34.50
Serial#		Appr Hrs	0.20	Appr Labor Amt \$23.00
	Notes			

Approved for .20

Labor

Line# 4

Operation Code

RC-042-05-00-004214

Operational Description

22V556, 2022-368 - LCI AWNINGS 22E-055 - INSPECTION ONLY - Recall/Awning/
Inspect/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2024-07-26 15:56:38 :: Complaint: Recall 22V556, 2022-368 LCI
Awnings 22E-055 Cause: Check for awning damage. 22V556, 2022-368 LCI Awning 22E-055 Correction: Awning
recall- inspection only.

Model#

Dlr Sub Hrs

0.30

Sub Labor Amt

\$34.50

Serial#

Appr Hrs

0.30

Appr Labor Amt

\$34.50

Notes

Submitted	Labor Amt	\$184.00	Approved	Labor Amt	\$172.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$184.00		Total	\$172.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.