

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10737

Date In:	01 JUL 24	Author:	MGRAY
Promised Date:	08 JUL 24	Stock No:	11096
:	:	Year:	2023
Customer Name:	17244 - HUFF, DAVID	Manufacturer:	FOREST RIVER
Address:	1131 90TH ST S	Brand:	PUMA TT
:	WISCONSIN RAPIDS, WI	Model:	24FBSC
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	7152133394	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	LJHDPH2@SOLARUS.NET	Tag#:	:
Purchased Date:	04 MAR 24	:	:
Delivery Date:	12 MAR 24	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUNB7P4018079	:	:

```
*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - WHEN SHOWER IS          W    1021    FORES
          TURNED ON, WATER IS BARELY COMING OUT.
          IT IS DRIBBLING OUT. WHEN REMOVED SHOWER
          HEAD, WATER COMING FROM THE HOSE WAS
          WEAK AS WELL.
          CAUSE:      Stating flow restriction at Showerhead.
                     Tested for first time barely trickling
                     out of Showerhead. Pulled Showerhead
                     supply hose apart and found small
                     fragments of plastic caught in flow
                     restrictor. Design of faucet allows
                     for line supplying Showerhead to drain
                     when off. Diaphragm was getting stuck
                     not allowing full flow to Showerhead.
                     Removed fancy pieces obstructing flow
                     and used a small screw with silicone to
                     plug drain hole. Now working much
                     better. Should warranty faucet and
                     labor. Needs replacement faucet. NEED 1
                     HR FOR DIAG AND REPLACEMENT.
          CORRECTION: Replacing faucet with different brand.
                     Dura Faucet design is flawed.
WARR    COMPLAINT:  Floor linoleum damaged from slide corner W    1020    GRAND
          CAUSE:      When slide is all the way in rear corner
                     of slide dips into linoleum on floor.
                     Cut a chunk of flooring. Also footboard
                     on slide is not installed square or
                     flush. Poor workmanship. Ultimate
```

Continued on page 2

Work Order : 10737

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
cause was flap seal behind footboard
binding with linoleum floor when slide
dipped stretching flooring allowing
contact with edge of slide. NEED 3.5 HRS
FOR PREP AND REPAIR OF LINO.
CORRECTION: Removed kickboard and sweep seal at base
of slide. Trimmed 3/16" off bottom edge
of boards. Reapplied sweep seal.
Reinstalled kickboard. Heather did
floor repair. Looks great.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 8220050396 FAUCET 4" SATIN NICKEL SHO W-1021      1      9.71      9.71

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.00      115.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR RW      W-1021      0.40      115.00      46.00
ARR33 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.00      115.00      0.00
ARR33 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.21      115.00      24.15
ARR33 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.87      115.00      100.05
ARR33 Z992      MISC LABOUR CODE (WARR RW      W-1020      0.92      115.00      105.80

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR33 SSE      SHOP SUPPLIES - EXTERNAL      W-1020      1.00      0.00      0.00

```

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      0.00      230.00      0.00      0.00      0.00      230.00
W      1021      9.71      46.00      0.00      0.00      0.00      55.71

Totals      9.71      276.00      0.00      0.00      0.00      285.71

```

&k2S
&k0S