

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10773

Date In: 08 JUL 24 Author: MGRAY
Promised Date: 05 AUG 24 Stock No: 10511
: Year: 2022
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN
Address: 11333 COUNTY RD 2 Brand: TRANSCEND XPLOR
: MIDDLEBURY, IN Model: 321BH
Postal/Zip: 46540 Miles/Hrs: 0
Phone#(res): 888-825-2820 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: NEED ENTERED FOR PRE A
Purchased Date: 11 AUG 23 :
Delivery Date: 18 AUG 23 :
InService Date: :
Serial#: 573TT3727N8821787 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	WARRANTY REPAIR 1 - HAS WALLS IN THE THE BUNK HOUSE THAT ARE BULGING OUT.		W	1020 GRAND
WARR	WARRANTY REPAIR 2 - AWNING FABRIC IS PULLING OUT OF THE TUBE. HAS ONLY USED THE AWNING 2 TIMES		W	1020 GRAND
WARR	WARRANTY REPAIR 3 - BOTH ENTRANCE DOORS ON FRONT HAVE LOCKING ISSUE. CODY AND JESS HAD NOTIFIED CMR AT ONE POINT ABOUT THE DOOR BEING OPEN WHEN DRIVING PASS DELIVERING OTHER UNIT. LOCKS BOTH DEAD BOLT AND MASTER LOCK AND DOOR STILL SOME TIMES ARE NOT LATCHING PROPERLY.		W	1020 GRAND
WARR	WARRANTY REPAIR 4 - IN THE BUNK ROOM THERE IS A SPOT NOTED WITH STICKER FOR TV MOUNT. WENT TO DRILL IN THE SPOT NOTED FOR TV MOUNT INSTALL AND THEY WENT STRAIGHT THROUGH THE WALL TO THE BATHROOM. WONDERING IF THERE IS AN ACTUAL STUD BACK THERE TO HOOK ON TOO.		W	1020 GRAND
WARR	WARRANTY REPAIR 5 - HAS A STICKER FOR THE TV MOUNT IN MASTER BEDROOM. WOULD LIKE VERIFICATION THAT IS IS THERE BEFORE TRYING TO MOUNT TV WITH POSSIBLE ISSUE IN THE BUNK HOUSE.		W	1020 GRAND
WARR	WARRANTY REPAIR 6 - Screen door on main entrance is busted. It never latched from the get go and I noticed this weeked that there is a busted bracket on the bottom.		W	1020 GRAND
WARR	WARRANTY REPAIR 7 - There are two smoke detectors that don't seem to work. The one in the living room doesn't do anything when you test it. The one in the main bedroom chirps constantly. I thought		W	1020 GRAND

Continued on page 2

Work Order : 10773

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
      maybe it needed a battery but it looks like they
      don't take batteries so not sure what the issue is.
      This has been the case since we first got it.

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR02 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR03 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR04 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR05 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR06 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00
ARR07 Z992     MISC LABOUR CODE (WARR      W-1020    0.00  115.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
Totals           0.00     0.00     0.00     0.00     0.00     0.00

```

&k2S
&k0S