



Warranty Claim Form

Date: 10/30/2024

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2626R3435693
Imagine 22RBE
Retail Purchase Date: 9/16/2023
Work Started: 10/8/2024
Work Completed: 10/8/2024

Claim Status: Paid
Dealer Work Order #: 10788
Unit Offline Date: 7/12/2023

Claim #: 845355
Labor: \$115.00
Parts: \$101.97
Shipping: \$25.16
Total: \$242.13

Notes: No vcb on 350044 - damage. NN 10.18 checking with vcb on 350044. NN 10.18

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$115.00

Customer Information

DALE HESSE
1312 RICHARDS AVENUE
WATERTOWN, Wisconsin 53094
United States
262-719-6690

Operation Line # 1

Flat Rate Code: 590019 Fender Skirts - Replace

Fault Code: Improper Installation/Build

Problem: Wheel wall panel is cracked.

Hours: .5

Cause: Fender skirt is cracked and needs to be replaced.

Amount: 57.50

Remedy: Request fender skit (570396)

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
570396 TRIM ABS TANDEM FENDER SKIRT FENDER SKIRT BLACK HC BLACK HAIR CELL TEXTURED IMAGINE EXPRESS	TRIM ABS TANDEM FENDER SKIRT BLACK HAIR CELL TEXTURED IMAGINE EXPRESS		2	1	87.54

Operation Line # 2

Flat Rate Code: 350044 Showers - R&R Shower Head

Fault Code: Damaged/Maintenance

Problem: Shower head has a crack where it screws into the hose.

Hours: .2

Cause: Shower head is cracked at the base of the handle and needs to be replaced.

Amount: 23.00

Remedy: Replaced shower handle.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
-------------	--------------------	---------------------	------------	--------------	---------------

960204 Miscellaneous Part for claim use only Miscellaneous Part for claim use only

1 1 14.43

Operation Line # 3

Flat Rate Code: 660017 Sliding Doors (wood/glass) - Repair *Fault Code:* Improper Installation/Build Door

Problem: Bedroom sliding door comes off the unit during travel.

Hours: .3

Cause: Sliding door started to sag due to screw coming loose.

Amount: 34.50

Remedy: Reattached the door frame. Checks okay.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: