

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10821B

Date In:	29 JUL 24	Author:	MGRAY
Promised Date:	31 DEC 24	Stock No:	11196
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	CROSSROADS
Address:	8220 STATE HWY 13 SOUT	Brand:	HAMPTON
:	WISCONSIN RAPIDS, WI	Model:	388FKL
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4YDTHPU20S9330033	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - On DAF the rear step W    1025    KEYST
        is bent
        CAUSE:      Bent on arrival Order 2 step steps for
        rear entrance WILL NEED .70 FRO REMOVE
        AND REPLACE.
        CORRECTION: NEED TO ORDER NEW STEPS FOR REAR
        ENTRANCE.
WARR    COMPLAINT:  WARRANTY REPAIR 2 - Unfilled holes on        W    1025    KEYST
        bottom exterior of slideroom floors
        CAUSE:      Mfg did not fill holes in exterior
        bottom of slide floors where screws went
        in WILL NEED .50 FOR REPAIRS
        CORRECTION: Cleaned all 4 slide room exterior bottom
        edges and then filled holes with black
        silicone
WARR    COMPLAINT:  WARRANTY REPAIR 3 - carpet has many          W    1025    KEYST
        strings and unfinished looking edges
        CAUSE:      Mfg layed carpet but left loose ends all
        over and it looks sloppy WILL NEED .80
        TO REMOVE ALL STRINGS IN UNIT.
        CORRECTION: I cut away loose carpet edges
WARR    COMPLAINT:  WARRANTY REPAIR 4 - slideroom floor          W    1025    KEYST
        coverings have stains
        CAUSE:      Stained from mfg WILL NEED .30 TO REMOVE
        STAINS TRHOUGHOUT UNIT.
        CORRECTION: Used cleaner to remove the spots on
        slideroom floor covering
WARR    COMPLAINT:  WARRANTY REPAIR 5 - Bedrooms step the        W    1025    KEYST
```

Continued on page 2

Work Order : 10821B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              face of step is pushed outward in one
              spot
      CAUSE:      Improper install
      CORRECTION: Please note with mfg in case future
                  customer is not happy with step in
                  bedroom
WARR      COMPLAINT: WARRANTY REPAIR 6 - on the monitor panel W      1025      KEYST
              one slideroom switch is not lying flat
      CAUSE:      Improve install mfg
      CORRECTION: Removed screws holding panel then pryed
                  the clips out a bit more from the slide
                  switch in back to hold it flush

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822093004 Step - Double - 24" - Radiu W-1025      0      108.11      0.00

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.50      105.00      52.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.36      105.00      37.80
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.14      105.00      14.70
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.50      105.00      52.50
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.50      105.00      52.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.50      105.00      52.50
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.50      105.00      52.50
ARR01 Z992      MISC LABOUR CODE (WARR      W-1025      0.00      105.00      0.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL      W-1025      1.00      0.00      0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1025      0.00      315.00      0.00      0.00      0.00      315.00

      Totals      0.00      315.00      0.00      0.00      0.00      315.00

```

&k2S
&k0S