

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10821B

Date In:	29 JUL 24	Author:	MGRAY
Promised Date:	31 DEC 24	Stock No:	11196
:	:	Year:	2025
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	CROSSROADS
Address:	8220 STATE HWY 13 SOUT	Brand:	HAMPTON
:	WISCONSIN RAPIDS, WI	Model:	388FKL
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	4YDTHPU20S9330033	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - On DAF the rear step I is bent	SEP	POLIC
	CAUSE:	Replace entrance steps on rear of unit. Arrived from factory bent.		
	CORRECTION:	Installed new steps on rear entrance.		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Unfilled holes on bottom exterior of slideroom floors	W	1025 KEYST
	CAUSE:	Mfg did not fill holes in exterior bottom of slide floors where screws went in WILL NEED .50 FOR REPAIRS		
	CORRECTION:	Cleaned all 4 slide room exterior bottom edges and then filled holes with black silicone		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - carpet has many strings and unfinished looking edges	W	1025 KEYST
	CAUSE:	Mfg layed carpet but left loose ends all over and it looks sloppy WILL NEED .80 TO REMOVE ALL STRINGS IN UNIT.		
	CORRECTION:	I cut away loose carpet edges		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - slideroom floor coverings have stains	W	1025 KEYST
	CAUSE:	Stained from mfg WILL NEED .30 TO REMOVE STAINS TRHOUGHOUT UNIT.		
	CORRECTION:	Used cleaner to remove the spots on slideroom floor covering		
WARR	COMPLAINT:	WARRANTY REPAIR 5 - Bedrooms step the face of step is pushed outward in one spot	W	1025 KEYST

Continued on page 2

Work Order : 10821B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
      CAUSE:      Improper install
      CORRECTION: Please note with mfg in case future
                  customer is not happy with step in
                  bedroom
WARR      COMPLAINT: WARRANTY REPAIR 6 - on the monitor panel W      1025      KEYST
                  one slideroom switch is not lying flat
      CAUSE:      Improve install mfg
      CORRECTION: Removed screws holding panel then pryed
                  the clips out a bit more from the slide
                  switch in back to hold it flush

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
WARR0 822093004 Step - Double - 24" - Radiu I-SEP      1      99.79      99.79

```

```

*****
Job# Lab Code      Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD I-SEP      0.50      70.00      35.00
ARR01 Z992      MISC LABOUR CODE (WARR TD I-SEP      0.10      70.00      7.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.22      105.00      23.10
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.08      105.00      8.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.80      105.00      84.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.30      105.00      31.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.30      105.00      31.50
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1025      0.20      105.00      21.00

```

```

*****
Job # Excode      Description      EXTRAS      bill to      Qty      Price      Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL      I-SEP      1.00      0.00      0.00
ARR01 FRT      FREIGHT      I-SEP      1.00      63.36      63.36

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      SEP      99.79      42.00      0.00      63.36      0.00      205.15
W      1025      0.00      199.50      0.00      0.00      0.00      199.50

Totals      99.79      241.50      0.00      63.36      0.00      404.65

```

&k2S
&k0S