

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10828

Date In:	16 JUL 24	Author:	MGRAY
Promised Date:	25 DEC 24	Stock No:	10974
:	:	Year:	2024
Customer Name:	15412 - PHILLIPS, EVER	Manufacturer:	GRAND DESIGN
Address:	868 SHEFFIELD COURT	Brand:	IMAGINE XLS
:	NEKOOSA, WI	Model:	22MLE
Postal/Zip:	54457	Miles/Hrs:	:
Phone#(res):	317-639-9845	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	EVERETT.C.PHILLIPS@GMA	Tag#:	:
Purchased Date:	29 JUL 23	:	:
Delivery Date:	29 SEP 23	:	:
InService Date:	:	:	:
Serial#:	573TE2624R3436373	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
BBI     COMPLAINT:  BRAKE AND BEARING INSPECTION - unit has E    15412  PHILL
        been 5-6k miles. ***CUSTOMER APPROVES
        REPACK IF NEEDED***
        CAUSE:      Bearing inspection.
        CORRECTION: Bearings and brakes look like new yet.
RI      COMPLAINT:  PREFORM ROOF INSPECTION AND ADVISE IF I    SEP    POLIC
        REPAIR IS NEEDED. ***MAKE SURE VENT
        COVERS ARE SECURE***
        CAUSE:      Roof inspection.
        CORRECTION: Perform roof inspection and checked to
        make sure vent covers are secure all
        good.
3       COMPLAINT:  check all slide seals to verify they are E    15412  PHILL
        in good shape.
        CAUSE:      Check slide seals for condition.
        CORRECTION: All seals look good. Also resyncronize
        slide motors. Tested good.
5       hard promise of 20th E    15412  PHILL
6       COMPLAINT:  hitch issue that was discussed with W    1020   GRAND
        Randy and Matt. ONE OF THE SAFETY CHAINS
        COMPLETELY SNAPPED-
        CAUSE:      Safety chain repair. WILL NEED .50 TO
        REPAIR CHAINS SO THEY ARE SAFE FOR
        CUSTOMER TO USE.
        CORRECTION: Installed extra chain links for repair.
1       COMPLAINT:  CUSTOMER STATES THAT RED LIGHTS ON THE W    1020   GRAND
        REAR OF THE UNIT ARE CRACKED- CUSTOMER
        WOULD LIKE INSPECTED AND REPLACED IF IN
```

Continued on page 2

Work Order : 10828

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                FACT CRACKED-
    CAUSE:    Rear clearance lights in top are all
                cracked. WILL NEED .50 TO REMOVE AND
                REPLACE ALL LENSES x 5
    CORRECTION: Install all new clearance lens.
2  COMPLAINT:  CUSTOMER STATES THAT THE DRAWER GLIDE      W      1020    GRAND
                FELL APART ON THE DRAWER DIRECTLY BEHIND
                THE DINNETTE
    CAUSE:    The drawer glide fell apart. I removed
                the old glide and when I went to put the
                new guide in it won't slide into the
                metal sleeve. I cut the staples, removed
                the sleeve, put it on the guide and re
                attached it with screws. WILL NEED .80
                FOR REMOVAL, REPAIR, RECONSTRUCT AND
                REPLACEMENT OF DRAWER AND DRAWER GUIDES.

    CORRECTION: REPAIRED AND IS WORKING LIKE IT SHOULD.
4  COMPLAINT:  CUSTOMER STATES THAT THERE IS A LOOSE      W      1020    GRAND
                BATTEN STRIP BY THE DOOR-
    CAUSE:    The nails pulled through. I nailed it
                back on and puttied the holes. WILL NEED
                .30 FOR REMOVAL OF NAILS RESECURE AND
                PUTTY NEW NAILS AND BATTEN.
    CORRECTION: RESCURED WITH DIFFERENT NAILS AND
                PUTTIED THEM TO LOOK NICE.

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
1      822020759    LIGHT LENS MCL40/44 RED    W-1020      5        0.82      4.10
2      822057300    BEARING DRAWER GLD 18``    W-1020      1        7.06      7.06
BBI    153425        GLOBAL REPL. KEY #388      E-15412     1        5.64      5.64
BBI    014717396042 HTS STANDARD 10' SEWER H   E-15412     1        9.51      9.51

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
BBI BBI BEARING BRAKE INSPECTI TD E-15412 0.30 140.00 42.00
RI Z991 PREFORM ROOF INSPECTIO TD I-SEP 0.20 70.00 14.00
3 Z990 MISC LABOUR CODE (EXTE TD E-15412 0.50 130.00 65.00
6 WARR MANUFACTURER WARRANTY TD W-1020 0.40 115.00 46.00
1 WARR MANUFACTURER WARRANTY TD W-1020 0.30 115.00 34.50
2 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 115.00 57.50
4 WARR MANUFACTURER WARRANTY JGK W-1020 0.50 115.00 57.50
2 WARR MANUFACTURER WARRANTY JGK W-1020 0.00 115.00 0.00
4 WARR MANUFACTURER WARRANTY JGK W-1020 0.00 115.00 0.00

```

Continued on page 3

Work Order : 10828

```
*****
Job #   Sublet Description      SUBLET      bill to      Vendor      Total
*****
   6   WELD NEW SAFETY CHAIN LOOPS      W-1020    1763-CRANKY JA      792.00
*****
```

```
*****
Job #   Excode   Description      EXTRAS      bill to      Qty      Price      Total
*****
  BBI   SSE      SHOP SUPPLIES - EXTERNAL    E-15412      1.00      8.03      8.03
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    15412        15.15      107.00        0.00        8.03        7.20      137.38
I    SEP          0.00       14.00         0.00         0.00         0.00       14.00
W    1020        11.16      195.50       792.00         0.00         0.00     998.66

      Totals      26.31      316.50      792.00         8.03         7.20     1,150.04
*****
```

&k2S
&k0S