



Warranty Claim Form

Date: 8/14/2024

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TE3422P6644014

Imagine 2970RL

Retail Purchase Date: 4/8/2023

Work Started: 7/29/2024

Work Completed: 7/29/2024

Claim Status: Paid

Dealer Work Order #: 10876B

Unit Offline Date: 11/28/2022

Claim #: 825430

Labor: \$57.50

Parts: \$0.00

Shipping: \$0.00

Total: \$57.50

Notes: JR 8/6/24

Dealer Information

1127 Greeneway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

WILLIAM HORSTMANN
1001 LAWDALE DRIVE
BEAVER DAM, Wisconsin 53916
United States
920-382-0892

Operation Line # 1

Flat Rate Code: 170036 Slide Out Assembly - Bell Stop R&R *Fault Code:* Damaged/Maintenance

Problem: Customer states that there is a leak in the ODS slide out right by the window in the rear of the slide out. Customer states that there was a heavy rain and then there was water on the floor. When looking at the unit, the ODS top left corner of the slide out is not going in all the way. May need just a slide out adjustment. Only leaks when it's closed.

Hours: .5

Cause: Checked slide out for leaks. No pictures as it did not leak after adjustment and we did not run water over the unit to find the leak once we noticed the bell stop needed adjustment. *Amount:* 57.50

Remedy: Adjusted the bell stop for slide so it wouldn't pull the top for the slide out away from the seal. *No *S u b l e t* labor code for bell stop repair/adjustment. *Repairs:* \$0.00

Manufacturer #:

Model #:

Serial #: